

Table 1 - Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			Recommended Level = 10 ppb							Recommended Level = 10 ppb	
CATEGORY	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE RESULTS DATE			10/26/2024			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
			11/21/2024			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
DRINKING	JAX-2069-HALL-WFCA-FD	Fountain in lobby, high water fountain on left.	0.5	No	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	JAX-2069-HALL-WFCB-FD	Fountain in lobby, low water fountain on right.	0.5	No	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	JAX 2069-K-K-FD	Kitchen behind front desk. Sink in kitchen, brake room.	0.5	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-BATHW-HHW-FD	Lobby rest room sink W.	1.8	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069- BATH-M/W-HHW-FD	Lobby rest room across from front desk	0.5	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-BATHW-MSHHWA-FD	Ladies restroom, sink with motion sensor.	0.5	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-BATHW-MSHHWB-FD	Ladies restroom, sink with motion sensor.	0.79	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-BATHM-HHW-FD	Lobby rest room M, sink.	1.7	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-BATHM-MSHHWA-FD	Men's restroom, sink with motion sensor.	0.5	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-BATHM-MSHHWB-FD	Men's restroom, sink with motion sensor.	0.57	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-RM1-RM-HHW-FD	First room on right. Education, yellow room.	0.5	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-RM2-RM-HHW-FD	Second room on right. Art, bleu room.	0.5	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-RM3-RM-HHW-FD	Third room on right. Science, green room.	0.5	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-RM4-RM-HHW-FD	First room on left. Dramatic play, teal room.	0.5	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2069-RM5-RM-HHW-FD	Second room on left. Manipulative, orange room.	0.5	No	N/A	N/A	N/A	N/A		N/A	N/A
Notes: <sup>1</sup> Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 10 ppb. <sup>2</sup> Post-remediation sampling was initially conducted on N/A. Additional N/A were implemented and final results below recommended level of 10 ppb for sample collected on N/A are shown on the table.											

Table 2 - Summary of Statistics

Table 2. Summary Statistics

Table 2: Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS				POST REMEDIATION RESULTS
	Recommended Level = 10 ppb					
	First Draw	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling	First Draw	Follow up Flush - Collected 30 seconds after First Draw Sampling	First Draw	
Total Drinking	2	0	0	0	0	
Total Drinking > 10 ppb	0	0	0	0	0	
Total Cooking	1	0	0	0	0	
Total Cooking > 10 ppb	0	0	0	0	0	
Total Washing	12	0	0	0	0	
Total Washing > 10 ppb	0	0	0	0	0	
Total Samples	15	0	0	0	0	
Total Samples > 10 ppb	0	0	0	0	0	