

Priority Areas Lead Testing and Corrective Actions May 2018
Naval Air Station Mayport Teen Center Building 1326

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb							Recommended Level = 20ppb	
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			5/5/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			5/30/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
DRINKING	MYP-1326-HALL-WFC-FD (BLDG 1326-1)	Located in hallway below the "Information Center Bulletin Board"	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-1326-HALL-WFCA-FD (BLDG 1326-7)	Hallway	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	MYP-1326-K-K-FD (BLDG 1326-6)	Kitchen	1.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1326-WBATH-LHW-FD (BLDG 1326-2)	Women's Bathroom Left sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1326-WBATH-HHW-FD (BLDG 1326-3)	Women's Bathroom Right sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1326-MBATH-LHW-FD (BLDG 1326-4)	Men's Bathroom Left sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1326-MBATH-HHW-FD (BLDG 1326-5)	Men's Bathroom Right sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Notes:

¹ Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

² Post-remediation sampling was initially conducted on N/A. Additional N/A were implemented and final results below recommended level of 20ppb for sample collected on N/A are shown on the table.

Priority Areas Lead Testing and Corrective Actions May 2018
Naval Air Station Mayport Teen Center Building 1326

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 20ppb				Description	Recommended Level = 20ppb
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb) (See note 2)		Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			5/5/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			5/30/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS		RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	Recommended Level = 20ppb					
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)	
Total Drinking	2	0	0	0	0	
Total Drinking > 20 ppb	0	0	0	0	0	
Total Cook/Brush	1	0	0	0	0	
Total Cook/Brush > 20 ppb	0	0	0	0	0	
Total Washing	4	0	0	0	0	
Total Washing > 20 ppb	0	0	0	0	0	
Total Samples	7	0	0	0	0	
Total Samples > 20 ppb	0	0	0	0	0	