

Priority Areas Lead Testing and Corrective Actions May 2018
Naval Air Station Mayport Child Development Center Building 1960

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 20ppb				Description	Recommended Level = 20ppb
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb) (See note 2)		Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE RESULTS DATE			5/5/2018			mm/dd/yyyy	6/13/2018	6/13/2018		7/26/2018	
			5/30/2018			mm/dd/yyyy	6/14/2018	6/14/2018		8/10/2018	
DRINKING	MYP-1960-HALL-WFC-A-FD (BLDG 1960-1)	Hallway near lobby desk - Low fountain located near the entrance	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-1960-HALL-WFC-B-FD (BLDG 1960-2)	Hallway near lobby desk - Low fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MYP-1960-HALL-WFC-C-FD (BLDG 1960-3)	Hallway near lobby desk - High fountain	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	MYP-1960-RM108-K-K-A-FD (BLDG 1960-4)	Kitchen - Triple stainless steel sink used to wash dishes	2.2	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	MYP-1960-RM108-K-K-B-FD (BLDG 1960-5)	Kitchen - Triple stainless steel sink used to wash dishes	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	MYP-1960-RM108-K-HHW-FD (BLDG 1960-6)	Kitchen - Stainless steel handwashing sink	1.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	MYP-1960-RM108-K-K-C-FD (BLDG 1960-7)	Kitchen - Double sink used for food preparation	25	YES	18-Jun-18	N/A	15	1.3	Faucet was replaced on 7/6/18 due to exceedance.	5	0.31
WASHING	MYP-1960-RM111-RM-HHW-FD (BLDG 1960-8)	Toddler Room - Stainless steel sink	0.8	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM111-RM-LHW-A-FD (BLDG 1960-9)	Toddler Room - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM111-RM-LHW-B-FD (BLDG 1960-10)	Toddler Room - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM112-RM-HHW-FD (BLDG 1960-11)	Toddler Room 2 - Stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM112-RM-LHW-A-FD (BLDG 1960-12)	Toddler Room 2 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM112-RM-LHW-B-FD (BLDG 1960-13)	Toddler Room 2 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM113-RM-HHW-FD (BLDG 1960-14)	Toddler Room 3 - Stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM113-RM-LHW-A-FD (BLDG 1960-15)	Toddler Room 3 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM113-RM-LHW-B-FD (BLDG 1960-16)	Toddler Room 3 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM114-RM-HHW-FD (BLDG 1960-17)	Toddler Room 4 - Stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM114-RM-LHW-A-FD (BLDG 1960-18)	Toddler Room 4 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM114-RM-LHW-B-FD (BLDG 1960-19)	Toddler Room 4 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions May 2018
Naval Air Station Mayport Child Development Center Building 1960

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 20ppb				Description	First Draw (ppb) (See note 2)
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)			
SAMPLING DATE			5/5/2018			mm/dd/yyyy	6/13/2018	6/13/2018		7/26/2018	
RESULTS DATE			5/30/2018			mm/dd/yyyy	6/14/2018	6/14/2018		8/10/2018	
WASHING	MYP-1960-RM116-RM-LHW-A-FD (BLDG 1960-20)	Preschool 3 - End of Hall, childs bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM116-RM-LHW-B-FD (BLDG 1960-21)	Preschool 3 - End of Hall, childs bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM116-RM-HHW-FD (BLDG 1960-22)	Preschool 3 - End of Hall, stainless steel sink	0.72	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM117-RM-HHW-FD (BLDG 1960-24)	Preschool 2 - Stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM117-RM-LHW-A-FD (BLDG 1960-25)	Preschool 2 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM117-RM-LHW-B-FD (BLDG 1960-26)	Preschool 2 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM118-RM-LHW-A-FD (BLDG 1960-27)	Preschool 1 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM118-RM-LHW-B-FD (BLDG 1960-28)	Preschool 1 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM118-RM-HHW-FD (BLDG 1960-29)	Preschool 1 - Stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM120-BATH-HHW-A-FD (BLDG 1960-30)	Women's Bathroom - Restroom sink on left	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM120-BATH-HHW-B-FD (BLDG 1960-31)	Women's Bathroom - Restroom sink on right	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM120-BATH-HHW-C (BLDG 1960-32)	Women's Bathroom - Handicap bathroom	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM121-BATH-HHW-A-FD (BLDG 1960-33)	Men's Bathroom - Handicap bathroom	1.5	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM121-BATH-HHW-B-FD (BLDG 1960-34)	Men's Bathroom - Restroom sink on left	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM121-BATH-HHW-C-FD (BLDG 1960-35)	Men's Bathroom - Restroom sink on right	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM122-RM-HHW-A-FD (BLDG 1960-36)	Infant 1 - Sink on left	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM122-RM-HHW-B-FD (BLDG 1960-37)	Infant 1 - Sink on right	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM129-RM-HHW-A-FD (BLDG 1960-38)	Infant 2 - Sink on left	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM129-RM-HHW-B-FD (BLDG 1960-39)	Infant 2 - Sink on right	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM130-LOUNGE-K (BLDG 1960-40)	Staff Breakroom - Stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions May 2018
Naval Air Station Mayport Child Development Center Building 1960

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)		Recommended Level = 20ppb	
mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy									
SAMPLING DATE			5/5/2018			mm/dd/yyyy	6/13/2018	6/13/2018		7/26/2018	
RESULTS DATE			5/30/2018			mm/dd/yyyy	6/14/2018	6/14/2018		8/10/2018	
WASHING	MYP-1960-RM128-RM-HHW-A-FD (BLDG 1960-41)	Infant 4 - Sink on left	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM128-RM-HHW-B-FD (BLDG 1960-42)	Infant 4 - Sink on right	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM123-RM-HHW-A-FD (BLDG 1960-43)	Infant 3 - Sink on left	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM123-RM-HHW-B-FD (BLDG 1960-44)	Infant 3 - Sink on right	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM127-RM-LHW-A-FD (BLDG 1960-45)	Pre-toddler 3 - Across from room 124, child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A	Faucet was proactively replaced on 7/17/18.	0.84	N/A
WASHING	MYP-1960-RM127-RM-LHW-B-FD (BLDG 1960-46)	Pre-toddler 3 - Across from room 124, child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A	Faucet was proactively replaced on 7/17/18.	0.84	N/A
WASHING	MYP-1960-RM127-RM-HHW-FD (BLDG 1960-47)	Pre-toddler 3 - Across from room 124, stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM125-RM-LHW-A-FD (BLDG 1960-48)	Pre-toddler 3 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM124-RM-HHW-FD (BLDG 1960-49)	Classroom used as storage area	3.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM124-RM-LM-LHW-A-FD (BLDG 1960-50)	Classroom used as storage area	11	NO	N/A	N/A	N/A	N/A	Faucet was proactively replaced on 7/23/18.	1.7	N/A
WASHING	MYP-1960-RM124-RM-LM-LHW-B-FD (BLDG 1960-51)	Classroom used as storage area	160	YES	18-Jun-18	N/A	91	1.5	Faucet was replaced on 7/23/18 due to exceedance.	2.1	0.39
WASHING	MYP-1960-RM125-RM-LHW-B-FD (BLDG 1960-52)	Pre-toddler 1 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM125-RM-HHW-FD (BLDG 1960-53)	Pre-toddler 1 - Stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM126-RM-LHW-A-FD (BLDG 1960-54)	Pre-toddler 2 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM126-RM-LHW-B-FD (BLDG 1960-55)	Pre-toddler 2 - Child's bathroom sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MYP-1960-RM126-RM-HHW-FD (BLDG 1960-56)	Pre-toddler 2 - Stainless steel sink	non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Notes:

¹ Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

² Post-remediation sampling was initially conducted on N/A. Additional routine control measures such as aerator cleaning were implemented and final results below recommended level of 20ppb for sample collected on N/A are shown on the table.

Priority Areas Lead Testing and Corrective Actions May 2018
Naval Air Station Mayport Child Development Center Building 1960

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 20ppb				Description	Recommended Level = 20ppb
						Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb) (See note 2)		Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			5/5/2018			mm/dd/yyyy	6/13/2018	6/13/2018		7/26/2018	
RESULTS DATE			5/30/2018			mm/dd/yyyy	6/14/2018	6/14/2018		8/10/2018	

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)
Total Drinking	3	0	0	0	0
Total Drinking > 20 ppb	0	0	0	0	0
Total Cook/Brush	4	0	1	1	1
Total Cook/Brush > 20 ppb	1	0	0	0	0
Total Washing	48	0	1	1	4
Total Washing > 20 ppb	1	0	1	0	0
Total Samples	55	0	2	2	5
Total Samples > 20 ppb	2	0	1	0	0