

Priority Areas Lead Testing and Corrective Actions September 2018
Naval Support Activity MID-SOUTH Child Development Center Building 943

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 20ppb				Description	First Draw (ppb) (See note 2)
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)			
SAMPLING DATE			8/18/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy			
RESULTS DATE			9/7/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy			mm/dd/yyyy
DRINKING	MDS-943-RM113-RM-WFCOMB-FD (BLDG 943-3)	Toddler Room Combo water fountain	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-943-RM113-RM-HWCOMB-FD (BLDG 943-4)	Toddler Room Combo Sink	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-943-RM110-RM-WFCOMB-FD (BLDG 943-9)	Pre-School Room Combo Water Fountain	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-943-RM110-RM-HWCOMB-FD (BLDG 943-10)	Pre-School Room Combo Sink	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-943-RM109-RM-WFCOMB-FD (BLDG 943-15)	Pre-School Room Combo Water Fountain	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-943-RM109-RM-HWCOMB-FD (BLDG 943-16)	Pre-School Combo Sink	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-943-RM106-RM-WFCOMB-FD (BLDG 943-21)	Pre-School Room Combo Water Fountain	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-943-RM106-RM-HWCOMB-FD (BLDG 943-22)	Pre-School Room Combo Sink	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-943-RM132-HALL-WFCA-FD (BLDG 943-26)	Fountain by Infant Rooms/Laundry Room High fountain left	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-943-RM132-HALL-WFCB-FD (BLDG 943-27)	Fountain by Infant Rooms/Laundry Room Low fountain right	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-943-RM136-RM-WFCOMB-FD (BLDG 943-29)	Toddler Room High classroom sink Combo water fountain	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-943-RM136-RM-HWCOMB-FD (BLDG 943-30)	Toddler Room Combo sink	Not Detected								
COOKING	MDS-943-RM114-LOUNGE-K-FD (BLDG 943-1)	Staff Breakroom kitchen sink	3.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM113-RM-HHWA-FD (BLDG 943-2)	Toddler Room High classroom sink	1.5	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM113-RM-HHWB-FD (BLDG 943-5)	Toddler Room High classroom sink by changing station	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
Washing	MDS-943-RM113-RM-MS-LHWA-FD (BLDG 943-6)	Toddler Room - Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions September 2018
Naval Support Activity MID-SOUTH Child Development Center Building 943

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)		Recommended Level = 20ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy
SAMPLING DATE			8/18/2018				mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	
RESULTS DATE			9/7/2018				mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	
Washing	MDS-943-RM113-RM-MS-LHWA-FD (BLDG 943-7)	Toddler Room - Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM110-RM-HHWA-FD (BLDG 943-8)	Pre-School Room High classroom sink	0.74	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM110-RM-HHWA-FD (BLDG 943-11)	Pre-School Room High classroom sink by changing station	0.85	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM110-RM-MS-LHWA-FD (BLDG 943-12)	Pre-School Room Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM110-RM-MS-LHWA-FD (BLDG 943-13)	Pre-School Room Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM109-RM-HHWA-FD (BLDG 943-14)	Pre-School Room Combo Sink	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM109-RM-HHWA-FD (BLDG 943-17)	Pre-School High Classroom Sink by Changing Station	1.4	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM109-RM-MS-LHWA-FD (BLDG 943-18)	Pre-School Room Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM109-RM-MS-LHWA-FD (BLDG 943-19)	Pre-School Room Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM106-RM-HHWA-FD (BLDG 943-20)	Pre-School Room High Classroom Sink	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM106-RM-HHWA-FD (BLDG 943-23)	Pre-School Room - High classroom sink by changing station	0.84	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM106-RM-MS-LHWA-FD (BLDG 943-24)	Pre-School Room Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM106-RM-MS-LHWA-FD (BLDG 943-25)	Pre-School Room Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions September 2018
Naval Support Activity MID-SOUTH Child Development Center Building 943

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)		Recommended Level = 20ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy
SAMPLING DATE			8/18/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			9/7/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
WASHING	MDS-943-RM136-RM-HHWA-FD (BLDG 943-28)	Toddler Room High classroom sink	1.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM136-RM-HHWA-FD (BLDG 943-31)	Toddler Room High classroom sink by changing station	1.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM136-RM-MS-LHWA-FD (BLDG 943-32)	Toddler Room Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM136-RM-MS-LHWA-FD (BLDG 943-33)	Toddler Room Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM137-RM-HHWA-FD (BLDG 943-34)	Pre-Toddler Room High classroom sink	1.5	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM137-RM-HHWA-FD (BLDG 943-35)	Pre-Toddler Room High classroom sink	1.9	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM137-RM-MS-LHW-FD (BLDG 943-36)	Pre-Toddler Room Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM145-RM-HHWA-FD (BLDG 943-37)	Pre-Toddler Room High classroom sink	1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM145-RM-HHWA-FD (BLDG 943-38)	Pre-Toddler Room High classroom sink	0.89	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM145-RM-MS-LHW-FD (BLDG 943-39)	Pre-Toddler Room Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM146-RM-HHWA-FD (BLDG 943-40)	Pre-Toddler Room High classroom sink	0.99	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM146-RM-HHWA-FD (BLDG 943-41)	Pre-Toddler Room High classroom sink	1.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM146-RM-MS-LHW-FD (BLDG 943-42)	Pre-Toddler Room Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM156-RM-HHWA-FD (BLDG 943-43)	Pre-Toddler Room High classroom sink	1.4	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM156-RM-HHWA-FD (BLDG 943-44)	Pre-Toddler Room High classroom sink	1.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM156-RM-MS-LHW-FD (BLDG 943-45)	Pre-Toddler Room Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM153-K-KA-FD (BLDG 943-46)	Side by side dishwashing sink in kitchen	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM153-K-KB-FD (BLDG 943-47)	Side by side dishwashing sink in kitchen	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions September 2018
 Naval Support Activity MID-SOUTH Child Development Center Building 943

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)		Recommended Level = 20ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy
SAMPLING DATE			8/18/2018				mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		
RESULTS DATE			9/7/2018				mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		
WASHING	MDS-943-RM153-K-HHWA-FD (BLDG 943-48)	Handwash sink by kitchen sinks	1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM153-K-HHWA-FD (BLDG 943-49)	Stand-alone handwash sink	2.5	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM149-RM-HHWA-FD (BLDG 943-50)	Infant Room -High Classroom Sink	1.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM149-RM-HHWA-FD (BLDG 943-51)	Infant Room -High Classroom Sink	1.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM149-RM-MS-LHW-FD (BLDG 943-52)	Infant Room Motion Sensor	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM142-RM-HHWA-FD (BLDG 943-53)	Infant Room High Classroom Sink	0.72	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM142-RM-HHWA-FD (BLDG 943-54)	Infant Room High Classroom Sink	1.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM142-RM-MS-LHW-FD (BLDG 943-55)	Infant Room Motion Sensor	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM141-RM-HHWA-FD (BLDG 943-56)	Infant Room High Classroom Sink	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM141-RM-HHWA-FD (BLDG 943-57)	Infant Room High Classroom Sink	0.81	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM141-RM-MS-LHW-FD (BLDG 943-58)	Infant Room Motion Sensor	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM133-RM-HHWA-FD (BLDG 943-59)	Infant Room High Classroom Sink	0.84	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM133-RM-HHWA-FD (BLDG 943-60)	Infant Room High Classroom Sink	1.2	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM133-RM-MS-LHW-FD (BLDG 943-61)	Infant Room Motion Sensor	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM116-UBATH-MS- HHWA-FD (BLDG 943-62)	Unisex bathroom beside break room on left Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	MDS-943-RM115-UBATH-MS- HHWA-FD (BLDG 943-63)	Unisex bathroom beside break room on right Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions September 2018
 Naval Support Activity MID-SOUTH Child Development Center Building 943

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 20ppb				Description	First Draw (ppb) (See note 2)
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)			
SAMPLING DATE			8/18/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy			mm/dd/yyyy
RESULTS DATE			9/7/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy			mm/dd/yyyy
WASHING	MDS-943-RM129-UBATH-MS-HHW-FD (BLDG 943-64)	Unisex bathroom beside janitor closet across water fountains Motion Sensor Faucet	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A

Notes:

¹ Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

² Post-remediation sampling was initially conducted on N/A. Additional N/A were implemented and final results below recommended level of 20ppb for sample collected on N/A are shown on the table.

Priority Areas Lead Testing and Corrective Actions September 2018
Naval Support Activity MID-SOUTH Child Development Center Building 943

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 20ppb				Description	First Draw (ppb) (See note 2)
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)			
SAMPLING DATE			8/18/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			9/7/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)
Total Drinking	12	0	0	0	0
Total Drinking > 20 ppb	0	0	0	0	0
Total Cook/Brush	1	0	0	0	0
Total Cook/Brush > 20 ppb	0	0	0	0	0
Total Washing	51	0	0	0	0
Total Washing > 20 ppb	0	0	0	0	0
Total Samples	64	0	0	0	0
Total Samples > 20 ppb	0	0	0	0	0