Table 1. Summary of Results

Г	SAMPLING LOCATION DESCRIPTION			INITIA	L SAMPLING			MPLING RESU	LTS	CORRECTIVE ACTIONS			
\vdash	CATEGORY SAMPLE Quitlet Description			T -		ded Level = 20ppb	I			Recommeded Level = 20ppb			
	CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
	SAMPLING DATE			5/19/2018			mm/dd/yyyy	mm/dd/ww	mm/dd/yyyy			mm/dd/yyyy	
	RESULTS DATE			6/5/2018			mm/dd/yyyy		mm/dd/yyyy			mm/dd/yyyy	
	DRINKING	KB-152-HALL-WFC-FD (BLDG 152- 1)	Fountain by entrance/lobby	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
	DRINKING	KB-152-RM152-RM-WFCOMBA-FD (BLDG 152-3)	Pre-K Room E Combo, water fountain on left	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
	DRINKING	KB-152-RM152-RM-WFCOMBB-FD (BLDG 152-5)	Pre-K Room E Combo, water fountain on right	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
	DRINKING	KB-152-RM152-RM-WFC-FD (BLDG 152-6)	Fountain by rear entrance Outside water fountain	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
	DRINKING	KB-152-RM137-RM-WFCOMBA-FD (BLDG 152-8)		Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
	DRINKING	KB-152-RM137-RM-WFCOMBB-FD (BLDG 152-10)	Pre-K2 Room D Combo, water fountain on right	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
	DRINKING	KB-152-RM160-RM-WFCOMB-FD (BLDG 152-14)	Infant Room 3, Combo, Water Fountain	Non-Detect	No								
	DRINKING	KB-152-RM157-RM-WFCOMB-FD (BLDG 152-18)		Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
	DRINKING	KB-152-RM150-RM-WFCOMBA-FD (BLDG 152-20)	Pre-K 1, room F Combo, water fountain on left	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
	WASHING	KB-152-RM161-RM-WFCOMB-FD (BLDG 152-26)	Infant Room 2, combo water fountain	1.2	No	N/A	N/A	N/A	N/A		N/A	N/A	
	DRINKING	KB-152-RM150-RM-WFCOMBB-FD (BLDG 152-22)		Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
	DRINKING	KB-152-RM160-RM-WFB-FD (BLDG 152-27)	Fountain outside back entrance Outside water fountain	3	No	N/A	N/A	N/A	N/A		N/A	N/A	
	DRINKING	KB-152-RM164-RM-WFCOMB-FD (BLDG 152-31)		0.96	No	N/A	N/A	N/A	N/A		N/A	N/A	

Priority Areas Lead Testing and Corrective Actions July 2018 NSB KINGS BAY Child Development Center Buildings 152

	INITIA	L SAMPLING			MPLING RESU	LTS	CORRECTIVE ACTIONS		POST REMEDIATION SAMPLING RESULTS		
		T -				ded Level = 20ppb					meded Level = 20ppb
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			5/19/2018			mm/dd/yyyy	mm/dd/sas	mm/dd/yyyy			mm/dd/yyyy
RESULTS DATE			6/5/2018			mm/dd/yyyy		mm/dd/yyyy			mm/dd/yyyy
COOKING	KB-152-RM125-K-HHW-FD (BLDG	Kitchen sink	2.4	No	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	152-36) KB-152-RM125-K-KA-FD (BLDG 152-37)	Double kitchen sink on left	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	KB-152-RM125-K-KB-FD (BLDG 152-38)	Double kitchen sink on right	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KB-152-RM152-RM-HWCOMBA- FD (BLDG 152-2)	Pre-K Room E Combo, high hand wash on left	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KB-152-RM152-RM-HWCOMBB- FD (BLDG 152-4)	Pre-K Room E Combo, high hand wash on right	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KB-152-RM137-RM-HWCOMBA- FD (BLDG 152-7)	Pre-K2 Room D Combo, high hand wash on left	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KB-152-RM137-RM-HWCOMBB- FD (BLDG 152-9)	Pre-K2 Room D Combo, high hand wash on right	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KB-152-RM160-RM-HHWA-FD (BLDG 152-11)	Infant Room 3 High hand wash	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KB-152-RM160-RM-HHWB-FD (BLDG 152-12)	Infant Room 3 High hand wash	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KB-152-RM160-RM-HWCOMB-FD (BLDG 152-13)	Infant Room 3 Combo, high hand wash	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KB-152-RM157-RM-HHWA-FD (BLDG 152-15)	Infant Room 4 High hand wash	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	(BLDG 152-15) KB-152-RM157-RM-HHWB-FD (BLDG 152-16)	Infant Room 4 High hand wash	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KB-152-RM157-RM-HWCOMB-FD (BLDG 152-17)	Infant Room 4 Combo, high hand wash	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KB-152-RM150-RM-HWCOMBA- FD (BLDG 152-19)	Pre-K 1, room F Combo, high hand wash on left	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A

SAMPLING LOCATION DESCRIPTION			INITIA	SAMPLING	RESULTS	RE-SA	MPLING RESU	LTS	CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS Recommeded Level = 20ppb	
					Recommed	led Level = 20ppb					
CATEGORY	SAMPLE	Outlet Description	First Draw	Retest	Date Fixture	Water Fountain	First Draw	Follow up	Description	First Draw	Follow up Flush
Water Intended For:	ID		(ppb)	required?	Secured?	15 min. Follow up	(ppb)	Flush		(ppb)	- Collected 30 seconds after
					(See Note 1)	Flush Sample -		- Collected 30		(See note 2)	First Draw Sampling
						Collected day		seconds after			(ppb)
						before First Draw		First Draw			
						Sampling		Sampling			
						(ppb)		(ppb)			
SAMPLING DATE			5/19/2018			mm/dd/yyyy	mm/dd/yyy	mm/dd/yyyy			mm/dd/yyyy
RESULTS DATE			6/5/2018			mm/dd/yyyy	mm/dd/yyy	mm/dd/yyyy			mm/dd/yyyy
WASHING	KB-152-RM150-RM-HWCOMBB-	Pre-K 1, room F Combo, high	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
	FD	hand wash on right									
	(BLDG 152-21)										
WASHING	KB-152-RM161-RM-HHWA-FD	Infant Room 2 High hand wash	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
	(BLDG 152-23)										
WASHING	KB-152-RM161-RM-HHWB-FD	Infant Room 2 High hand wash	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
	(BLDG 152-24)										

SAMPLING LOCATION DESCRIPTION				L SAMPLING	RESULTS	RE-SAI	MPLING RESU	LTS	CORRECTIVE ACTIONS	POST REMED	POST REMEDIATION SAMPLING RESULTS	
	Recommeded Level = 20ppb							Recom	Recommeded Level = 20ppb			
CATEGORY	SAMPLE	Outlet Description	First Draw	Retest	Date Fixture	Water Fountain	First Draw	Follow up	Description	First Draw	Follow up Flush	
Water Intended For:	ID		(ppb)	required?	Secured?	15 min. Follow up	(ppb)	Flush		(ppb)	- Collected 30 seconds after	
					(See Note 1)	Flush Sample -		- Collected 30		(See note 2)	First Draw Sampling	
						Collected day		seconds after			(ppb)	
						before First Draw		First Draw				
						Sampling		Sampling				
						(ppb)		(ppb)				
SAMPLING DATE			5/19/2018			mm/dd/yyyy	mm/dd/vvv	mm/dd/yyyy			mm/dd/yyyy	
RESULTS DATE			6/5/2018			mm/dd/yyyy		mm/dd/yyyy			mm/dd/yyyy	
WASHING	KB-152-RM161-RM-HWCOMB-FD	Infant Room 2 Combo, high	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
	(BLDG 152-25)	hand wash				,		,		,	•	
	, ,											
WASHING	KB-152-RM164-RM-HHWA-FD	Infant Room 1 High hand wash	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
	(BLDG 152-28)											
WASHING	KB-152-RM164-RM-HHWB-FD	Infant Room 1 High hand wash	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
	(BLDG 152-29)											
WASHING	KB-152-RM164-RM-HWCOMB-FD		Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
	(BLDG 152-30)	hand wash										
WASHING	KB-152-BATH-HHWA-FD (BLDG	Unisex restroom by entrance	1.1	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	152-32)	sink	1.1	INO	IN/A	IN/A	IN/A	N/A		IN/A	N/A	
WASHING	KB-152-BATH-HHWB-FD (BLDG	Unisex restroom by supply	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	152-33)	room sink	14011-Detect	INO	18/7	IN/A	11/7	IV/ A		IN/A	N/A	
Washing	KB-152-BATH-HHWC-FD (BLDG	Unisex Restroom, Restroom			N/A	N/A	N/A	N/A		N/A	N/A	
	252 5 1111110 15 (5250	ooccot. oom, nestroom	l	1	,,,,	,,,,	1,,,,	,,,		1 11//1	14//	

Notes:

¹ Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

² Post-remediation sampling was initially conducted on N/A. Additional N/A were implemented and final results below recommended level of 20ppb for sample collected on N/A are shown on the table.

Si	SAMPLING LOCATION DESCRIPTION		INITIAL SAMPLING RESULTS RE-SAMPLING RESULTS					LTS	CORRECTIVE ACTIONS	POST REMED	DIATION SAMPLING RESULTS
					Recommed	led Level = 20ppb			Recommeded Level = 20ppb		nmeded Level = 20ppb
CATEGORY	SAMPLE	Outlet Description	First Draw	Retest	Date Fixture	Water Fountain	First Draw	Follow up	Description	First Draw	Follow up Flush
Water Intended For:	ID		(ppb)	required?	Secured?	15 min. Follow up	(ppb)	Flush		(ppb)	- Collected 30 seconds after
					(See Note 1)	Flush Sample -		- Collected 30		(See note 2)	First Draw Sampling
						Collected day		seconds after			(ppb)
						before First Draw		First Draw			
						Sampling		Sampling			
						(ppb)		(ppb)			
SAMPLING DATE			5/19/2018			mm/dd/yyyy	mm/dd/yyy	mm/dd/yyyy			mm/dd/yyyy
RESULTS DATE			6/5/2018			mm/dd/yyyy	mm/dd/yyy	mm/dd/yyyy			mm/dd/yyyy

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS		POST REMEDIATION RESULTS								
	Recommeded Level = 20ppb										
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)						
Total Drinking	13	0	0	0	0						
Total Drinking > 20 ppb	0	0	0	0	0						
Total Cook/Brush	3	0	0	0	0						
Total Cook/Brush > 20 ppb	0	0	0	0	0						
Total Washing	20	0	0	0	0						
Total Washing > 20 ppb	0	0	0	0	0						
Total Samples	36	0	0	0	0						
Total Samples > 20 ppb	0	0	0	0	0						