Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIA	L SAMPLING	RESULTS	RE-SAN	/IPLING RESU	LTS	CORRECTIVE ACTIONS P		POST REMEDIATION SAMPLING RESULTS	
		Recommended Level = 15 ppb							Recom	mended Level = 15 ppb		
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
SAMPLING DATE			6/8/2019			mm/dd/yyyy					mm/dd/yyyy	
RESULTS DATE			6/24/2019			mm/dd/yyyy					mm/dd/yyyy	
DRINKING	NOLA-561-RM106-HALL-WFCA-	Fountain beside snack bar -	1.4	NO	N/A	N/A	N/A	N/A		N/A	N/A	
	FD (BLDG 561-2)	Drinking fountain										
DRINKING	NOLA-561-RM106-HALL-WFCB-	Fountain beside snack bar -	1.4	NO	N/A	N/A	N/A	N/A		N/A	N/A	
	FD (BLDG 561-3)	Drinking fountain										
DRINKING	NOLA-561-RM110-HALL-WFCA		0.9	NO	N/A	N/A	N/A	N/A		N/A	N/A	
	FD (BLDG 561-13)	Bathroom - Water Fountain										
DRINKING	NOLA-561-RM110-HALL-WFCB-		0.87	NO	N/A	N/A	N/A	N/A		N/A	N/A	
000///10	FD (BLDG 561-14)	Bathroom - Water Fountain	1.0			21/2	2.0	4.0		21/2	21/2	
COOKING	NOLA-561-RM104-K-K-FD (BLDG 561-1)	Snack Bar - Food prep Sink	1.2			N/A	2.8	4.3		N/A	N/A	
COOKING	NOLA-561-RM113-LOUNGE-K-	Taschar's launga/hraskroom	6.9	NO	N/A	N/A	N/A	N/A		N/A	N/A	
COOKING	FD (BLDG 561-6)	Kitchen sink in lounge/breakroom	0.9	NO	N/A	N/A	N/A	N/A		IN/A	N/A	
COOKING	NOLA-561-RM121-RM-K-FD (BLDG 561-15)	Activity Room 1 (Orange room) - Food prep Sink	0.8	NO	N/A	N/A	N/A	N/A		N/A	N/A	
COOKING	NOLA-561-RM123-RM-K-FD	Activity Room 3 (Blue Room) -	1.1	NO	N/A	N/A	N/A	N/A		N/A	N/A	
COOKING	(BLDG 561-16)	Food prep Sink	1.1	140	IV/A	IN/A	IN/A	N/A		IN/A	N/A	
COOKING		Activity Room 4 (Purple room) -	1.0	NO	N/A	N/A	N/A	N/A		N/A	N/A	
	(BLDG 561-17)	Food prep Sink			.,	,	,	.,,		,		
COOKING		Activity Room 2 (Green room) -	1.4	NO	N/A	N/A	N/A	N/A		N/A	N/A	
	(BLDG 561-18)	Food prep Sink										

SAMPLING LOCATION DESCRIPTION			INITIAI	SAMPLING	RESULTS	RE-SAM	MPLING RESU	ILTS	CORRECTIVE ACTIONS	CORRECTIVE ACTIONS POST REMEDIATION SAMPLING RESULTS		
					Recommen	ded Level = 15 ppb				Recommended Level = 15 ppb		
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
SAMPLING DATE			6/8/2019			mm/dd/yyyy					mm/dd/yyyy	
RESULTS DATE			6/24/2019			mm/dd/yyyy					mm/dd/yyyy	
WASHING	NOLA-561-RM108-BATH-HHW-	Bathroom sink - Unisex	1.1	NO	N/A	N/A	N/A	N/A		N/A	N/A	
	FD (BLDG 561-4)	bathroom										
WASHING	NOLA-561-RM107-BATH-HHW-	Bathroom sink - Unisex	1.5	NO	N/A	N/A	N/A	N/A		N/A	N/A	
	FD (BLDG 561-5)	bathroom										
WASHING	NOLA-561-RM117-BATH-	Boys' Bathroom - Handwash	1.0	NO	N/A	N/A	N/A	N/A		N/A	N/A	
	HHWA-FD (BLDG 561-7)	Sink										
WASHING	NOLA-561-RM117-BATH-	Boys' Bathroom - Handwash	1.2	NO	N/A	N/A	N/A	N/A		N/A	N/A	
	HHWB-FD (BLDG 561-8)	Sink										
WASHING	NOLA-561-RM117-BATH-	Boys' Bathroom - Handwash	1.3	NO	N/A	N/A	N/A	N/A		N/A	N/A	
	HHWC-FD (BLDG 561-9)	Sink										
WASHING	NOLA-561-RM118-BATH-	Girls' Bathroom - Handwash	1.1	NO	N/A	N/A	N/A	N/A		N/A	N/A	
	HHWA-FD (BLDG 561-10)	Sink										
WASHING	NOLA-561-RM118-BATH-	Girls' Bathroom - Handwash	0.91	NO	N/A	N/A	N/A	N/A		N/A	N/A	
	HHWB-FD (BLDG 561-11)	Sink										
WASHING	NOLA-561-RM118-BATH-	Girls' Bathroom - Handwash	0.8	NO	N/A	N/A	N/A	N/A		N/A	N/A	
	HHWC-FD (BLDG 561-12)	Sink										

Notes:

SAMPLING LOCATION DESCRIPTION		INITIAL SAMPLING RESULTS		RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS			
				Recommende						Recommended Level = 15 ppb	
CATEGORY	SAMPLE	Outlet Description	First Draw	Retest	Date Fixture	Water Fountain	First Draw	Follow up	Description	First Draw	Follow up Flush
Water Intended For:	ID		(ppb)	required?	Secured?	15 min. Follow up	(ppb)	Flush		(ppb)	- Collected 30 seconds after
					(See Note 1)	Flush Sample -		- Collected 30		(See note 2)	First Draw Sampling
						Collected day		seconds after			(ppb)
						before First Draw		First Draw		1	
						Sampling		Sampling		1	
						(ppb)		(ppb)		1	
										1	
										1	
										1	
										1	
SAMPLING DATE			6/8/2019			mm/dd/yyyy	İ			1	mm/dd/yyyy
RESULTS DATE			6/24/2019			mm/dd/yyyy					mm/dd/yyyy

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS		RE-SAMPLING RESULTS	POST REMEDIATION RESULTS								
		Recommended Level = 15 ppb										
	First Draw (ppb)	Water Fountain	First Draw (ppb)	Follow up Flush	First Draw (ppb)							
Total Drinking												
	4	0	0	0	0							
Total Drinking > 15 ppb	0	0	0	0	0							
Total Cook/Brush	6	0	1	1	0							
Total Cook/Brush > 15 ppb	0	0	0	0	0							
Total Washing	8	0	0	0	0							
Total Washing > 15 ppb	0	0	0	0	0							
Total Samples	18	0	1	1	0							
Total Samples > 15 ppb	0	0	0	0	0							