

Priority Areas Lead Testing and Corrective Actions July 2018
NSB KINGS BAY CRAB

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)		Description	First Draw (ppb) (See note 2)
SAMPLING DATE			5/19/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			6/5/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
DRINKING	KB-1066-HALL-WFC-A-FD (BLDG 1066-2)	Cooler Fountain to the right of entrance	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	KB-1066-HALL-WFC-B-FD (BLDG 1066-3)	Bottle Filling Station to the Right of Entrance	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KB-1066-K-K-FD (BLDG 1066-1)	Kitchen Sink Adjacent to Party Room #1 and Starbucks	Non-Detect	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KB-1066-WBATH-HHW-A-FD (BLDG 1066-4)	Womens Bathroom, High Hand Wash	0.95	No	N/A	N/A	N/A	N/A			
WASHING	KB-1066-WBATH-HHW-B-FD (BLDG 1066-5)	Womens Bathroom, High Hand Wash	1.3	No	N/A	N/A	N/A	N/A			
WASHING	KB-1066-MBATH-HHW-A-FD (BLDG 1066-6)	Mens Bathroom, High Hand Wash	2.2	No	N/A	N/A	N/A	N/A			
WASHING	KB-1066-MBATH-HHW-B-FD (BLDG 1066-7)	Mens Bathroom, High Hand Wash	1.7	No	N/A	N/A	N/A	N/A			

Notes:

¹ Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

² Post-remediation sampling was initially conducted on N/A. Additional N/A were implemented and final results below recommended level of 20ppb for sample collected on N/A are shown on the table.

Priority Areas Lead Testing and Corrective Actions July 2018
NSB KINGS BAY CRAB

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS Description	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb							Recommended Level = 20ppb	
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
SAMPLING DATE			5/19/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		
RESULTS DATE			6/5/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	Recommended Level = 20ppb				
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)
Total Drinking	2	0	0	0	0
Total Drinking > 20 ppb	0	0	0	0	0
Total Cook/Brush	0	0	0	0	0
Total Cook/Brush > 20 ppb	0	0	0	0	0
Total Washing	5	0	0	0	0
Total Washing > 20 ppb	0	0	0	0	0
Total Samples	7	0	0	0	0
Total Samples > 20 ppb	0	0	0	0	0