

Priority Areas Lead Testing and Corrective Actions July 2018
NSB KINGS BAY Play Areas

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)		Recommended Level = 20ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy
SAMPLING DATE			5/19/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy			mm/dd/yyyy
RESULTS DATE			6/5/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy			mm/dd/yyyy
DRINKING	KB-PLAY-WFBA-FD (PLAY-1)	Soccer Complex Stands by Faucet - Water fountain at soccer complex	1	NO	N/A	N/A	N/A	N/A			N/A
DRINKING	KB-PLAY-WFCA-FD (PLAY-2)	Soccer Complex Restroom Building - Water fountain at building with restrooms	0.92	NO	N/A	N/A	N/A	N/A			N/A
DRINKING	KB-PLAY-WFCB-FD (PLAY-3)	Soccer Complex between restrooms - Water fountain at building with restrooms	Non-Detect	NO	N/A	N/A	N/A	N/A			N/A
DRINKING	KB-PLAY-WFBB-FD (PLAY-4)	Soccer Complex Standing Faucet - Water fountain at soccer complex	3.5	NO	N/A	N/A	N/A	N/A			N/A
DRINKING	KB-PLAY-1035-WFBA-FD (PLAY-5)	Ballfield Bldg 1035 houses restrooms and concession stand - Water fountain on left	Non-Detect	NO	N/A	N/A	N/A	N/A			N/A
DRINKING	KB-PLAY-1035-WFBB-FD (PLAY-6)	Ballfield Bldg 1035 houses restrooms and concession stand - Middle water fountain	Non-Detect	NO	N/A	N/A	N/A	N/A			N/A
DRINKING	KB-PLAY-1035-WFBC-FD (PLAY-7)	Ballfield Bldg 1035 houses restrooms and concession stand - Water fountain on right	Non-Detect	NO	N/A	N/A	N/A	N/A			N/A
DRINKING	KB-PLAY-TRACK-WFBA-FD (PLAY-8)	Fountain by Track	Non-Detect	NO	N/A	N/A	N/A	N/A			N/A
DRINKING	KB-PLAY-TRACK-WFBB-FD (PLAY-9)	Fountain by Track towards end of pond - Water fountain by track			N/A	N/A	N/A	N/A	Inoperable at Sample Event		N/A
DRINKING	KB-PLAY-BASKETBALL-WFB-FD (PLAY-10)	By basketball court - Water fountain by basketball court			N/A	N/A	N/A	N/A	Continuously running - not sampled		N/A
DRINKING	KB-PLAY-TENNIS-WFB-FD (PLAY-11)	By tennis court - Water fountain by tennis court	9	NO	N/A	N/A	N/A	N/A			N/A

Priority Areas Lead Testing and Corrective Actions July 2018
NSB KINGS BAY Play Areas

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)		Recommended Level = 20ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			5/19/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			6/5/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
DRINKING	KB-PLAY-156-WFBA-FD (PLAY-12)	Fountain at CCD ballfield concession stand - Water fountain near concession stand at baseball field by youth center.			N/A	N/A	N/A	N/A	Inoperable at Sample Event	N/A	N/A
DRINKING	KB-PLAY-156-WFBB-FD (PLAY-13)	Fountain at CCD ballfield concession stand - Fountain designed for disable access	1.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KB-PLAY-156-HOSE-FD (PLAY-14)	Hose bib at CCD ballfield concession stand - Hose bib on concession stand at ballfield near youth center	Non-Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KB-PLAY-156-HOSEB-FD (PLAY-15)	Hose bib at CCD ballfield concession stand - Hose bib on concession stand at ballfield near youth center next to PLAY-12	11	NO	N/A	N/A	N/A	N/A		N/A	N/A

Notes:

¹ Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

² Post-remediation sampling was initially conducted on N/A. Additional N/A were implemented and final results below recommended level of 20ppb for sample collected on N/A are shown on the table.

Priority Areas Lead Testing and Corrective Actions July 2018
NSB KINGS BAY Play Areas

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 20ppb				Description	Recommended Level = 20ppb
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb) (See note 2)		Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			5/19/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			6/5/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS		RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	Recommended Level = 20ppb					
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)	
Total Drinking	10	0	0	0	0	
Total Drinking > 20 ppb	0	0	0	0	0	
Total Cook/Brush	0	0	0	0	0	
Total Cook/Brush > 20 ppb	0	0	0	0	0	
Total Washing	2	0	0	0	0	
Total Washing > 20 ppb	0	0	0	0	0	
Total Samples	12	0	0	0	0	
Total Samples > 20 ppb	0	0	0	0	0	