

Priority Areas Lead Testing and Corrective Actions May 2019
NAS CORPUS CHRISTI Youth Center Building 1756

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 15 ppb							Recommended Level = 15 ppb	
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			5/16/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			6/5/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
DRINKING	CC-1756-HALL-WFC-FD (BLDG 1756-1)	Fountain by check-in desk - Water Fountain	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	CC-1756-PLAY-WFC-FD (BLDG 1756-2)	Fountain in gym - Water Fountain	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	CC-1756-K-K-FD (BLDG 1756-3)	Sink in kitchen - Kitchen Sink	1.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1756-BATH-M-MS-HHWA-FD (BLDG 1756-4)	Mens Room, Motion Sensor	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1756-BATH-M-MS-HHWA-FD (BLDG 1756-5)	Mens Room, Motion Sensor	1.2	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1756-BATH-W-MS-HHWA-FD (BLDG 1756-6)	Womens Room, Motion Sensor	2.5	No	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1756-BATH-W-MS-HHWA-FD (BLDG 1756-7)	Womens Room, Motion Sensor	2.7	No	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions May 2019
NAS CORPUS CHRISTI Youth Center Building 1756

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS		RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 15 ppb						Description	Recommended Level = 15 ppb
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)		First Draw (ppb) (See note 2)
SAMPLING DATE			5/16/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	
RESULTS DATE			6/5/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	Recommended Level = 15 ppb				
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)
Total Drinking	2	0	0	0	0
Total Drinking >15 ppb	0	0	0	0	0
Total Cook/Brush	1	0	0	0	0
Total Cook/Brush >15 ppb	0	0	0	0	0
Total Washing	4	0	0	0	0
Total Washing >15 ppb	0	0	0	0	0
Total Samples	7	0	0	0	0
Total Samples >15 ppb	0	0	0	0	0