

Priority Areas Lead Testing and Corrective Actions May 2019  
NAS CORPUS CHRISTI Child Development Center Building 1782

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 15 ppb							Description	Recommended Level = 15 ppb
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb) (See note 2)		Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
<b>SAMPLING DATE</b>			<b>5/16/2019</b>			<b>mm/dd/yyyy</b>	<b>6/13/2019</b>	<b>6/13/2019</b>		<b>9/5/2019</b>	
<b>RESULTS DATE</b>			<b>6/4/2019</b>			<b>mm/dd/yyyy</b>	<b>6/19/2019</b>	<b>6/19/2019</b>		<b>9/10/2019</b>	
DRINKING	CC-1782-HALL-WFC-FD (BLDG 1782-1)	Fountain by check-in desk - Water fountain	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	CC-1782-PLAY-WFBA-FD (BLDG 1782-4)	Fountain by outdoor play area on west side of building - Outside water fountain	6.8	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	CC-1782-PLAY-WFBB-FD (BLDG 1782-5)	Fountain by outdoor play area on south side of building - Outside water fountain	4.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
<del>DRINKING</del>	<del>CC-1782-HALL-WFC-B-FD (BLDG 1782-7)</del>	<del>Water fountain outside Starfish Room - Water fountain on left</del>		<del>NO</del>	<del>N/A</del>	<del>N/A</del>	<del>N/A</del>	<del>N/A</del>	Could Not Locate	<del>N/A</del>	<del>N/A</del>
<del>DRINKING</del>	<del>CC-1782-HALL-WFC-C-FD (BLDG 1782-8)</del>	<del>Water fountain outside Starfish Room - Water fountain on right</del>		<del>NO</del>	<del>N/A</del>	<del>N/A</del>	<del>N/A</del>	<del>N/A</del>	Could Not Locate	<del>N/A</del>	<del>N/A</del>
DRINKING	CC-1782-HALL-WFC-D-FD (BLDG 1782-11)	Water Fountain by Unisex Restrooms, Single Water Fountain	Non Detect								
COOKING	CC-1782-RM110-LOUNGE-K-FD (BLDG 1782-3)	Food prep sink in break room - Kitchen prep sink	2.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	CC-1782-RM125-K-K-FD (BLDG 1782-21)	Kitchen - Shared kitchen between Guppie and Seahorse rooms	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	CC-1782-RM111-K-K-FD (BLDG 1782-26)	Kitchen - Kitchen prep sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1782-RM107-BATH-UNISEX-HHW-FD (BLDG 1782-2)	Bathroom by reception/check-in desk - Bathroom sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1782-PLAY-HOSE-FD (BLDG 1782-6)	Hose spigot by outdoor play area on south side of building - Hose bib	4.9	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1782-RM103-BATH-UNISEX-HHW-FD (BLDG 1782-9)	Bathroom next to offices - Bathroom sink	0.72	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions May 2019  
NAS CORPUS CHRISTI Child Development Center Building 1782

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 15 ppb					
First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)				Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			5/16/2019			mm/dd/yyyy	6/13/2019	6/13/2019		9/5/2019	
RESULTS DATE			6/4/2019			mm/dd/yyyy	6/19/2019	6/19/2019		9/10/2019	
WASHING	CC-1782-RM104-BATH-UNISEX-HHW-FD (BLDG 1782-10)	Bathroom across back of Goldfish Room - Bathroom sink	2.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1782-RM116-RM-LHWA-FD (BLDG 1782-12)	Stingray Room - Low hand wash sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1782-RM116-RM-LHWB-FD (BLDG 1782-13)	Stingray Room - Low hand wash sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1782-RM116-RM-LHWC-FD (BLDG 1782-14)	Stingray Room - Low hand wash sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1782-RM122-RM-LHWA-FD (BLDG 1782-15)	Starfish Room - Low hand wash sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1782-RM122-RM-LHWB-FD (BLDG 1782-16)	Starfish Room - Low hand wash sink	150	Yes	6/5/2019	N/A	6.8	1.0	Faucet replaced on 7/26/19.	1.7	N/A
WASHING	CC-1782-RM122-RM-LHWC-FD (BLDG 1782-17)	Starfish Room - Low hand wash sink	7.8	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1782-RM127-RM-LHW-FD (BLDG 1782-18)	Guppie Room - Shared washroom between Guppie and Seahorse rooms	6.8	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1782-RM123-RM-LHW-FD (BLDG 1782-19)	Seahorse Room - Shared washroom between Guppie and Seahorse rooms	2.8	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1782-RM123-RM-HHW-FD (BLDG 1782-20)	Seahorse Room - Low hand wash sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1782-RM127-RM-HHW-FD (BLDG 1782-22)	Guppie Room - High hand wash sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions May 2019  
 NAS CORPUS CHRISTI Child Development Center Building 1782

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 15 ppb							Description	Recommended Level = 15 ppb
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb) (See note 2)		Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
<b>SAMPLING DATE</b>			5/16/2019			mm/dd/yyyy	6/13/2019	6/13/2019		9/5/2019	
<b>RESULTS DATE</b>			6/4/2019			mm/dd/yyyy	6/19/2019	6/19/2019		9/10/2019	
WASHING	CC-1782-RM115-RM-LHWA-FD (BLDG 1782-23)	Goldfish Room - Low hand wash sink	1.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1782-RM115-RM-LHWB-FD (BLDG 1782-24)	Goldfish Room - Low hand wash sink	0.94	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	CC-1782-RM115-RM-LHWC-FD (BLDG 1782-25)	Goldfish Room - Low hand wash sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Notes:

<sup>1</sup> Affected outlet was immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 15 ppb.

<sup>2</sup> Post-remediation sampling was conducted on 9/5/19 and final results did not exceed recommended level of 15 ppb.

Priority Areas Lead Testing and Corrective Actions May 2019  
NAS CORPUS CHRISTI Child Development Center Building 1782

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS		RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 15 ppb						Description	Recommended Level = 15 ppb
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)		First Draw (ppb) (See note 2)
SAMPLING DATE			5/16/2019			mm/dd/yyyy	6/13/2019	6/13/2019	9/5/2019	
RESULTS DATE			6/4/2019			mm/dd/yyyy	6/19/2019	6/19/2019	9/10/2019	

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)
Total Drinking	4	0	0	0	0
Total Drinking > 15 ppb	0	0	0	0	0
Total Cook/Brush	3	0	0	0	0
Total Cook/Brush > 15 ppb	0	0	0	0	0
Total Washing	17	0	1	1	1
Total Washing > 15 ppb	1	0	0	0	0
Total Samples	24	0	1	1	1
Total Samples > 15 ppb	1	0	0	0	0