

Priority Areas Lead Testing and Corrective Actions April 2019
NAS JACKSONVILLE Gym Building 2066

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			Recommended Level = 15 ppb							Recommended Level = 15 ppb	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			4/27/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			5/13/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
DRINKING-	JAX-2066-UT-ICE-FD (BLDG-2066-1)	Ice Machine Closet inside first room on left storage area		NO	N/A	N/A	N/A	N/A	-	N/A	N/A
DRINKING	JAX-2066-HALL-WFC-FD (BLDG 2066-2)	Water fountain in the hall	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2066-BATHM-HHWA-FD (BLDG 2066-3)	Male restroom sink left	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2066-BATHM-HHWA-FD (BLDG 2066-4)	Male restroom sink right	5.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2066-BATHW-HHWA-FD (BLDG 2066-5)	Women restroom sink left	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2066-BATHW-HHWA-FD (BLDG 2066-6)	Women restroom sink right	0.93	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2066-HOSE-FD (BLDG-2066-7)	Hose		NO	N/A	N/A	N/A	N/A	-	N/A	N/A

Notes:

¹ Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 15 ppb.

² Post-remediation sampling was initially conducted on N/A. Additional N/A were implemented and final results below recommended level of 15 ppb for sample collected on N/A are shown on the table.

Priority Areas Lead Testing and Corrective Actions April 2019
NAS JACKSONVILLE Gym Building 2066

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS		RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS		
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 15 ppb			Description	Recommended Level = 15 ppb	
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)		First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			4/27/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		
RESULTS DATE			5/13/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	Recommended Level = 15 ppb		First Draw (ppb)
First Draw (ppb)			Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)		
Total Drinking	1	0	0	0	0
Total Drinking > 15 ppb	0	0	0	0	0
Total Cook/Brush	0	0	0	0	0
Total Cook/Brush > 15 ppb	0	0	0	0	0
Total Washing	4	0	0	0	0
Total Washing > 15 ppb	0	0	0	0	0
Total Samples	5	0	0	0	0
Total Samples > 15 ppb	0	0	0	0	0