

Priority Areas Lead Testing and Corrective Actions April 2019  
NAS JACKSONVILLE Teen Center Building 2065

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 15 ppb					
First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)				Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
<b>SAMPLING DATE</b>			<b>4/27/2019</b>			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
<b>RESULTS DATE</b>			<b>5/13/2019</b>			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
DRINKING	JAX-2065-RM-WFC-FD (BLDG 2065-1)	Water fountain in open area	Non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2065-BATHM-HHWA-FD (BLDG 2065-2)	Male restroom sink Bathroom sink on left	6.4	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2065-BATHM-HHWA-FD (BLDG 2065-3)	Male restroom sink Bathroom sink on right	Non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2065-BATHW-HHWA-FD (BLDG 2065-4)	Women restroom sink Bathroom sink on left	Non-detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2065-BATHW-HHWA-FD (BLDG 2065-5)	Women restroom sink Bathroom sink on right	9.9	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2065-HOSE-FD (BLDG-2065-6)	Hose		NO	N/A	N/A	N/A	N/A	-	N/A	N/A

Notes:

<sup>1</sup> Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 15 ppb.

<sup>2</sup> Post-remediation sampling was initially conducted on N/A. Additional N/A were implemented and final results below recommended level of 15 ppb for sample collected on N/A are shown on the table.

Priority Areas Lead Testing and Corrective Actions April 2019  
NAS JACKSONVILLE Teen Center Building 2065

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 15 ppb				Description	First Draw (ppb) (See note 2)
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)			
SAMPLING DATE			4/27/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			5/13/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS		RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	Recommended Level = 15 ppb					First Draw (ppb)
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)	
Total Drinking	1	0	0	0	0	0
Total Drinking > 15 ppb	0	0	0	0	0	0
Total Cook/Brush	0	0	0	0	0	0
Total Cook/Brush > 15 ppb	0	0	0	0	0	0
Total Washing	4	0	0	0	0	0
Total Washing > 15 ppb	0	0	0	0	0	0
Total Samples	5	0	0	0	0	0
Total Samples > 15 ppb	0	0	0	0	0	0