## Priority Areas Lead Testing and Corrective Actions FY24 NAS Jacksonville Teen Center Building 2065

## Table 1 - Summary of Results

SAMPLING LOCATION DESCRIPTION				NITIAL SAMPLING RES	SULTS	RE-SA	MPLING RESULT	TS	CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS  Recommended Level = 10 ppb	
					Recommende	ed Level = 10 ppb					
CATEGORY	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			10/26/2024			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			11/21/2024			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy			mm/dd/yyyy
DRIKING	JAX-2065-RM-WFC-FD	Water fountain in open area.	0.5	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRIKING	JAX-2065-RM-BOTTLE-FD	Bottle filler on water fountain in open area.	0.5	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2065-BATHM-HHWA-FD	Male restroom sink, sink on left.	2.7	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2065-BATHM-HHWB-FD	Male restroom sink, sink on right.	0.72	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2065-BATHW-HHWA-FD	Women restroom sink, sink on left.	0.5	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	JAX-2065-BATHW-HHWB-FD	Women restroom sink, sink on right.	7	NO	N/A	N/A	N/A	N/A		N/A	N/A
otes:		1	1					1		1	_ I

Notes:

¹ Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 10 ppb.

<sup>&</sup>lt;sup>2</sup> Post-remediation sampling was initially conducted on N/A. Additional N/A were implemented and final results below recommended level of 10 ppb for sample collected on N/A are shown on the table.

## Priority Areas Lead Testing and Corrective Actions FY24 NAS Jacksonville Teen Center Building 2065

## Table 2 - Summary Statistics

	INITIAL SAMPLING RESULTS	RE-SAMPLII	POST REMEDIATION RESULTS						
CATEGORY	Recommended Level = 10 ppb								
	First Draw	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling	First Draw	Follow up Flush - Collected 30 seconds after First Draw Sampling	First Draw				
Total Drinking	2	0	0	0	0				
Total Drinking > 10 ppb	0	0	0	0	0				
Total Cooking	0	0	0	0	0				
Total Cooking > 10 ppb	0	0	0	0	0				
Total Washing	4	0	0	0	0				
Total Washing > 10 ppb	0	0	0	0	0				
Total Samples	6	0	0	0	0				
Total Samples > 10 ppb	0	0	0	0	0				