

Priority Areas Lead Testing and Corrective Actions June 2019
 NASJRB New Orleans Child Development Center Building 528

Table 1. Summary of Results

| SAMPLING LOCATION DESCRIPTION | | | INITIAL SAMPLING RESULTS | | | RE-SAMPLING RESULTS | | | CORRECTIVE ACTIONS | POST REMEDIATION SAMPLING RESULTS | |
|------------------------------------------------------------------------------------------------------------------|-------------------------------------------|------------------------------------------------------------------------------------------|---------------------------------|--------------|--------------------|---------------------|---------------------|------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------|-----|
| | | | CATEGORY Water Intended For: | SAMPLE ID | Outlet Description | First Draw (ppb) | Retest required? | Date Fixture Secured? (See Note 1) | | Recommended Level = 15 ppb | |
| Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb) | First Draw (ppb) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) | | | | | | | First Draw (ppb) (See note 2) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) | |
| SAMPLING DATE | | | 6/8/2019 | | | mm/dd/yyyy | 7/2/2019 | 7/2/2019 | | 8/22/2019 | |
| RESULTS DATE | | | 6/24/2019 | | | mm/dd/yyyy | 7/10/2019 | 7/10/2019 | | 8/30/2019 | |
| DRINKING | NOLA-528-RM123-RM-HHW-FD (BLDG 528-1) | Pre-school Activity Room 1 - High Handwash Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| DRINKING | NOLA-528-RM123-RM-WFCOMB-FD (BLDG 528-3) | Pre-school Activity Room 1 - Water Fountain in Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| DRINKING | NOLA-528-RM124-RM-WFCOMB-FD (BLDG 528-8) | Pre-school Activity Room 2 - Water Fountain in Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| DRINKING | NOLA-528-RM125-RM-WFCOMB-FD (BLDG 528-13) | Pre-school Activity Room 3 - Water Fountain in Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| DRINKING | NOLA-528-RM122-RM-WFCOMB-FD (BLDG 528-22) | Toddler Activity Room 2 - Water Fountain in Sink | | NO | N/A | N/A | N/A | N/A | Inoperable | N/A | N/A |
| DRINKING | NOLA-528-RM121-RM-WFCOMB-FD (BLDG 528-28) | Toddler Activity Room 1 - Water Fountain in Sink | | NO | N/A | N/A | N/A | N/A | Inoperable | N/A | N/A |
| DRINKING | NOLA-528-RM142-RM-WFCOMB-FD (BLDG 528-38) | Toddler Room 3 - Water Fountain in Sink | 1.3 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| DRINKING | NOLA-528-RM142-RM-WFC-FD (BLDG 528-39) | Toddler Room 3 - Fountain by bathrooms | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| DRINKING | NOLA-528-RM102-HALL-WFC-FD (BLDG 528-42) | Lobby by admin station - Fountain | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| DRINKING | NOLA-528-RM120-RM-WFCOMB-FD (BLDG 528-45) | Pre-Toddler Room 3 - Water Fountain in Sink | | NO | N/A | N/A | N/A | N/A | Inoperable | N/A | N/A |
| DRINKING | NOLA-528-RM119-RM-WFB-FD (BLDG 528-50) | Pre-Toddler Room 2 - Water Fountain in Sink | | NO | N/A | N/A | N/A | N/A | Inoperable | N/A | N/A |
| DRINKING | NOLA-528-RM138-RM-WFCOMB-FD (BLDG 528-55) | Pre-Toddler Room 1 - Water Fountain in Sink | 11 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| DRINKING | NOLA-528-RM137-RM-WFCOMB-FD (BLDG 528-61) | Toddlers 3 - Not in use (storage area) | 4.7 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |

Priority Areas Lead Testing and Corrective Actions June 2019
 NASJRB New Orleans Child Development Center Building 528

| SAMPLING LOCATION DESCRIPTION | | | INITIAL SAMPLING RESULTS | | | RE-SAMPLING RESULTS | | | CORRECTIVE ACTIONS | POST REMEDIATION SAMPLING RESULTS | |
|---------------------------------|--------------------------------------------------|------------------------------------------------|--------------------------|---------------------|------------------------------------------|------------------------------------------------------------------------------------------------------------------|---------------------|------------------------------------------------------------------------------------------|--------------------|-----------------------------------|-------------------------------------|
| CATEGORY Water Intended For: | SAMPLE ID | Outlet Description | First Draw (ppb) | Retest required? | Date Fixture Secured? (See Note 1) | Recommended Level = 15 ppb | | | | Description | First Draw (ppb) (See note 2) |
| | | | | | | Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb) | First Draw (ppb) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) | | | |
| SAMPLING DATE | | | 6/8/2019 | | | mm/dd/yyyy | 7/2/2019 | 7/2/2019 | | | 8/22/2019 |
| RESULTS DATE | | | 6/24/2019 | | | mm/dd/yyyy | 7/10/2019 | 7/10/2019 | | | 8/30/2019 |
| DRINKING | NOLA-528-RM132-RM- WFCOMB-FD (BLDG 528-69) | Pre-Toddler Room 3 - Water Fountain in Sink | | NO | N/A | N/A | N/A | N/A | Inoperable | N/A | N/A |

Priority Areas Lead Testing and Corrective Actions June 2019
NASJRB New Orleans Child Development Center Building 528

| SAMPLING LOCATION DESCRIPTION | | | INITIAL SAMPLING RESULTS | | | RE-SAMPLING RESULTS | | | CORRECTIVE ACTIONS | POST REMEDIATION SAMPLING RESULTS | |
|---------------------------------|----------------------------------------------------|------------------------------------------------------------|--------------------------|---------------------|------------------------------------------|------------------------------------------------------------------------------------------------------------------|---------------------|------------------------------------------------------------------------------------------|-------------------------------------|-----------------------------------|---------------------------------------------------------------------------------|
| CATEGORY Water Intended For: | SAMPLE ID | Outlet Description | First Draw (ppb) | Retest required? | Date Fixture Secured? (See Note 1) | Recommended Level = 15 ppb | | | | Description | Recommended Level = 15 ppb |
| | | | | | | Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb) | First Draw (ppb) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) | First Draw (ppb) (See note 2) | | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) |
| SAMPLING DATE | | | 6/8/2019 | | | mm/dd/yyyy | 7/2/2019 | 7/2/2019 | | 8/22/2019 | |
| RESULTS DATE | | | 6/24/2019 | | | mm/dd/yyyy | 7/10/2019 | 7/10/2019 | | 8/30/2019 | |
| COOKING | NOLA-528-RM130-K-KB-FD (BLDG 528-16) | Kitchen - Kitchen sink for dishwashing. | 1.8 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| COOKING | NOLA-528-RM130-K-KA-FD (BLDG 528-17) | Kitchen - Kitchen sink for food prep. | 0.81 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| COOKING | NOLA-528-RM130-K-HHWA- FD (BLDG 528-18) | Kitchen - Handwash Sink. | 0.71 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| COOKING | NOLA-528-RM130-K-HHWA- FD (BLDG 528-19) | Kitchen - Handwash Sink by utensils and dishes storage. | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| COOKING | NOLA-528-RM110-LOUNGE-K- FD (BLDG 528-32) | Break Room (Lounge) - Food prep Sink | 1.2 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM123-RM-LHW- FD (BLDG 528-2) | Pre-school Activity Room 1 - Low Handwash Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM123-RM-MS- LHW-A FD (BLDG 538-4) | Pre-school Activity Room 1, Motion Sensor | 1.2 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM123-RM-MS- LHW-B FD (BLDG 528-5) | Pre-school Activity Room 1, Motion Sensor | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM124-RM-HHW- FD (BLDG 528-6) | Pre-school Activity Room 2 - High Handwash Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM124-RM-LHW- FD (BLDG 528-7) | Pre-school Activity Room 2 - Low Handwash Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM124-RM-MS- LHW-A FD (BLDG 528-9) | Pre-school Activity Room 2, Motion Sensor | 1.5 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM124-RM-MS- LHW-B FD (BLDG 528-10) | Pre-school Activity Room 2, Motion Sensor | 1.3 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM125-RM-HHW- FD (BLDG 528-11) | Pre-school Activity Room 3 - High Handwash Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM125-RM-LHW- FD (BLDG 528-12) | Pre-school Activity Room 3 - Low Handwash Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM125-RM-MS- LHW-A FD (BLDG 528-14) | Pre-school Activity Room 3, Motion Sensor | 1.1 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |

Priority Areas Lead Testing and Corrective Actions June 2019
 NASJRB New Orleans Child Development Center Building 528

| SAMPLING LOCATION DESCRIPTION | | | INITIAL SAMPLING RESULTS | | | RE-SAMPLING RESULTS | | | CORRECTIVE ACTIONS | POST REMEDIATION SAMPLING RESULTS | |
|-------------------------------|------------------------------------------------|-------------------------------------------------|---------------------------------|--------------|--------------------|------------------------------------------------------------------------------------------------|------------------|------------------------------------------------------------------------|--------------------|-----------------------------------|------------------------------------------------------------------------|
| | | | CATEGORY Water Intended For: | SAMPLE ID | Outlet Description | Recommended Level = 15 ppb | | | | | Recommended Level = 15 ppb |
| First Draw (ppb) | Retest required? | Date Fixture Secured? (See Note 1) | | | | Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb) | First Draw (ppb) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) | Description | First Draw (ppb) (See note 2) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) |
| SAMPLING DATE | | | 6/8/2019 | | | mm/dd/yyyy | 7/2/2019 | 7/2/2019 | | 8/22/2019 | |
| RESULTS DATE | | | 6/24/2019 | | | mm/dd/yyyy | 7/10/2019 | 7/10/2019 | | 8/30/2019 | |
| WASHING | NOLA-528-RM125-RM-MS-LHW-B FD (BLDG 528-15) | Pre-school Activity Room 3 , Motion Sensor | 1.3 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM122-RM-HHW-FD (BLDG 528-20) | Toddler Activity Room 2 - High Handwash Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM122-RM-LHW-FD (BLDG 528-21) | Toddler Activity Room 2 - Low Handwash Sink | | NO | N/A | N/A | N/A | N/A | Inoperable | N/A | N/A |
| WASHING | NOLA-528-RM122-RM-MS-LHW-A FD (BLDG 528-23) | Toddler Activity Room 2 , Motion Sensor | 1.9 | | | | | | | | |
| WASHING | NOLA-528-RM122-RM-MS-LHW-B FD (BLDG 528-24) | Toddler Activity Room 2 , Motion Sensor | 2.8 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM122-RM-MS-LHW-B FD (BLDG 528-25) | Toddler Activity Room 2, Motion Sensor | 0.85 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM121-RM-HHW-FD (BLDG 528-26) | Toddler Activity Room 1 - High Handwash Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM121-RM-LHW-FD (BLDG 528-27) | Toddler Activity Room 1 - Low Handwash Sink | | NO | N/A | N/A | N/A | N/A | Inoperable | N/A | N/A |
| WASHING | NOLA-528-RM121-RM-MS-LHW-A FD (BLDG 528-29) | Toddler Activity Room 1 | 1.3 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM121-RM-MS-LHW-B FD (BLDG 528-30) | Toddler Activity Room 1 | 2.5 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM121-RM-MS-HHW FD (BLDG 528-31) | Toddler Activity Room 1 | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM112-BATH-MS-HHW FD (BLDG 528-33) | Bathroom by Lounge on Left , Motion Sensor | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM113-BATH-MS-HHW FD (BLDG 528-34) | Bathroom by Lounge in the Middle, Motion Sensor | 2 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |

Priority Areas Lead Testing and Corrective Actions June 2019
 NASJRB New Orleans Child Development Center Building 528

| SAMPLING LOCATION DESCRIPTION | | | INITIAL SAMPLING RESULTS | | | RE-SAMPLING RESULTS | | | CORRECTIVE ACTIONS | POST REMEDIATION SAMPLING RESULTS | |
|---------------------------------|------------------------------------------------|---------------------------------------------|----------------------------|------------------|------------------------------------|------------------------------------------------------------------------------------------------|------------------|------------------------------------------------------------------------|--------------------|-----------------------------------|------------------------------------------------------------------------|
| CATEGORY Water Intended For: | SAMPLE ID | Outlet Description | Recommended Level = 15 ppb | | | | | | | Recommended Level = 15 ppb | |
| | | | First Draw (ppb) | Retest required? | Date Fixture Secured? (See Note 1) | Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb) | First Draw (ppb) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) | Description | First Draw (ppb) (See note 2) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) |
| SAMPLING DATE | | | 6/8/2019 | | | mm/dd/yyyy | 7/2/2019 | 7/2/2019 | | 8/22/2019 | |
| RESULTS DATE | | | 6/24/2019 | | | mm/dd/yyyy | 7/10/2019 | 7/10/2019 | | 8/30/2019 | |
| WASHING | NOLA-528-RM114-BATH-MS-HHW FD (BLDG 528-35) | Bathroom by Lounge on Right , Motion Sensor | 1.5 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM142-RM-HHW-FD (BLDG 528-36)) | Toddler Room 3 - High Handwash Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM142-RM-LHW-FD (BLDG 528-37)) | Toddler Room 3 - Low Handwash Sink | 6.1 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM142-RM-MS-LHW-A FD (BLDG 528-40) | Toddler Room 3 , Motion Sensor | 1.4 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM142-RM-MS-LHW-B FD (BLDG 528-41) | Toddler Room 3 , Motion Sensor | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM120-RM-HHW-FD (BLDG 528-43) | Pre-Toddler Room 3 - High Handwash Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |

Priority Areas Lead Testing and Corrective Actions June 2019
NASJRB New Orleans Child Development Center Building 528

| SAMPLING LOCATION DESCRIPTION | | | INITIAL SAMPLING RESULTS | | | RE-SAMPLING RESULTS | | | CORRECTIVE ACTIONS | POST REMEDIATION SAMPLING RESULTS | |
|------------------------------------------------------------------------------------------------|---------------------------------------------|------------------------------------------------------------------------|---------------------------------|-----------|--------------------|---------------------|------------------|------------------------------------|------------------------------|-----------------------------------|------------------------------------------------------------------------|
| | | | CATEGORY Water Intended For: | SAMPLE ID | Outlet Description | First Draw (ppb) | Retest required? | Date Fixture Secured? (See Note 1) | | Recommended Level = 15 ppb | |
| Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb) | First Draw (ppb) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) | | | | | | | Description | First Draw (ppb) (See note 2) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) |
| SAMPLING DATE | | | 6/8/2019 | | | mm/dd/yyyy | 7/2/2019 | 7/2/2019 | | 8/22/2019 | |
| RESULTS DATE | | | 6/24/2019 | | | mm/dd/yyyy | 7/10/2019 | 7/10/2019 | | 8/30/2019 | |
| WASHING | NOLA-528-RM120-RM-LHW-FD (BLDG 528-44) | Pre-Toddler Room 3 - Low Handwash Sink (turned off) | | NO | N/A | N/A | N/A | N/A | Inoperable | N/A | N/A |
| WASHING | NOLA-528-RM120-RM-MS-LHW FD (BLDG 528-46) | Pre-Toddler Room 1 , Motion Sensor | 1.5 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM120-RM-MS-HHW FD (BLDG 528-47) | Pre-Toddler Room 1 , Motion Sensor | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM119-RM-HHW-FD (BLDG 528-48) | Pre-Toddler Room 2 - High Handwash Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM119-RM-LHW-FD (BLDG 528-49) | Pre-Toddler Room 2 - Low Handwash Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM119-RM-MS-LHW FD (BLDG 528-51) | Pre-Toddler Room 2 , Motion Sensor | 2.1 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM119-RM-MS-HHW FD (BLDG 528-52) | Pre-Toddler Room 2 , Motion Sensor | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM138-RM-HHW-FD (BLDG 528-53) | Pre-Toddler Room 1 - High Handwash Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM138-RM-LHW-FD (BLDG 528-54) | Pre-Toddler Room 1 - Low Handwash Sink | | NO | N/A | N/A | N/A | N/A | Inoperable | N/A | N/A |
| WASHING | NOLA-528-RM138-RM-MS-LHW-A FD (BLDG 528-56) | Pre-Toddler Room 4 , Motion Sensor | 2 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM138-RM-MS-LHW-B FD (BLDG 528-57) | Pre-Toddler Room 4 , Motion Sensor | 3.6 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM138-RM-MS-HHW FD (BLDG 528-58) | Pre-Toddler Room 4 , Motion Sensor | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM137-RM-HHW-FD (BLDG 528-59) | Toddlers 3 - Not in use (storage area) | Non Detect | NO | N/A | N/A | N/A | N/A | | 1.2 | N/A |
| WASHING | NOLA-528-RM137-RM-LHW-FD (BLDG 528-60) | Toddlers 3 - Not in use (storage area) | 44 | YES | 6/24/2019 | N/A | 32 | 4.1 | Fixture replaced on 7/23/19. | Non Detect | N/A |

Priority Areas Lead Testing and Corrective Actions June 2019
 NASJRB New Orleans Child Development Center Building 528

| SAMPLING LOCATION DESCRIPTION | | | INITIAL SAMPLING RESULTS | | | RE-SAMPLING RESULTS | | | CORRECTIVE ACTIONS | POST REMEDIATION SAMPLING RESULTS | |
|-------------------------------|------------------------------------------------|-----------------------------------------------|---------------------------------|-----------|--------------------|---------------------|------------------|------------------------------------|------------------------------------------------------------------------------------------------|-----------------------------------|------------------------------------------------------------------------|
| | | | CATEGORY Water Intended For: | SAMPLE ID | Outlet Description | First Draw (ppb) | Retest required? | Date Fixture Secured? (See Note 1) | | Recommended Level = 15 ppb | |
| | | | | | | | | | Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb) | First Draw (ppb) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) |
| SAMPLING DATE | | | 6/8/2019 | | | mm/dd/yyyy | 7/2/2019 | 7/2/2019 | | 8/22/2019 | |
| RESULTS DATE | | | 6/24/2019 | | | mm/dd/yyyy | 7/10/2019 | 7/10/2019 | | 8/30/2019 | |
| WASHING | NOLA-528-RM137-RM-MS-LHW-A FD (BLDG 528-62) | Toddlers 3 , Motion Sensor | 5.1 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM137-RM-MS-LHW-B FD (BLDG 528-63) | Toddlers 3 , Motion Sensor | 1.9 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM137-RM-MS-HHW FD (BLDG 528-64) | Toddlers 3 , Motion Sensor | 7.8 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM134-BATH-MS-HHW FD (BLDG 528-65) | Bathroom by Room 137 on Left , Motion Sensor | 0.87 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM135-BATH-MS-HHW FD (BLDG 528-66) | Bathroom by Room 137 on Right , Motion Sensor | 1.4 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM132-RM-HHW-FD (BLDG 528-67) | Pre-Toddler Room 3 - High Handwash Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM132-RM-LHW-FD (BLDG 528-68) | Pre-Toddler Room 3 - Low Handwash Sink | | NO | N/A | N/A | N/A | N/A | Inoperable | N/A | N/A |
| WASHING | NOLA-528-RM132-RM-MS-LHW FD (BLDG 528-70) | Pre-Toddler Room 3, Motion Sensor | 1.7 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM132-RM-MS-HHW FD (BLDG 528-71) | Pre-Toddler Room 3 , Motion Sensor | 1.7 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM131-RM-HHW-FD (BLDG 528-72) | Infant Room 3 - High Handwash Sink | 2.1 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM131-RM-MS-LHW FD (BLDG 528-73) | Infant Room 3 , Motion Sensor | 2.4 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM131-RM-MS-HHW FD (BLDG 528-74) | Infant Room 3 , Motion Sensor | | NO | N/A | N/A | N/A | N/A | Inoperable | N/A | N/A |
| WASHING | NOLA-528-RM117-RM-HHW-FD (BLDG 528-75) | Infant Room 2 - High Handwash Sink | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |

Priority Areas Lead Testing and Corrective Actions June 2019
 NASJRB New Orleans Child Development Center Building 528

| SAMPLING LOCATION DESCRIPTION | | | INITIAL SAMPLING RESULTS | | | RE-SAMPLING RESULTS | | | CORRECTIVE ACTIONS | POST REMEDIATION SAMPLING RESULTS | |
|---------------------------------|----------------------------------------------|------------------------------------|----------------------------|---------------------|------------------------------------------|------------------------------------------------------------------------------------------------------------------|---------------------|------------------------------------------------------------------------------------------|--------------------|-------------------------------------|---------------------------------------------------------------------------------|
| CATEGORY Water Intended For: | SAMPLE ID | Outlet Description | Recommended Level = 15 ppb | | | | | | | Recommended Level = 15 ppb | |
| | | | First Draw (ppb) | Retest required? | Date Fixture Secured? (See Note 1) | Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb) | First Draw (ppb) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) | Description | First Draw (ppb) (See note 2) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) |
| SAMPLING DATE | | | 6/8/2019 | | | mm/dd/yyyy | 7/2/2019 | 7/2/2019 | | 8/22/2019 | |
| RESULTS DATE | | | 6/24/2019 | | | mm/dd/yyyy | 7/10/2019 | 7/10/2019 | | 8/30/2019 | |
| WASHING | NOLA-528-RM117-RM-MS-LHW FD (BLDG 528-76) | Infant Room 2 , Motion Sensor | | NO | N/A | N/A | N/A | N/A | Inoperable | N/A | N/A |
| WASHING | NOLA-528-RM117-RM-MS-HHW FD (BLDG 528-77) | Infant Room 2 , Motion Sensor | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM118-RM-HHW-FD (BLDG 528-78) | Infant Room 1 - High Handwash Sink | 2.2 | NO | N/A | N/A | N/A | N/A | | N/A | N/A |
| WASHING | NOLA-528-RM118-RM-MS-LHW FD (BLDG 528-79) | Infant Room 1 , Motion Sensor | | NO | N/A | N/A | N/A | N/A | Inoperable | N/A | N/A |
| WASHING | NOLA-528-RM118-RM-MS-HHW FD (BLDG 528-80) | Infant Room 1 , Motion Sensor | Non Detect | NO | N/A | N/A | N/A | N/A | | N/A | N/A |

Notes:
¹ Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 15 ppb.
² Post-remediation sampling was conducted on 8/22/19.

Priority Areas Lead Testing and Corrective Actions June 2019
 NASJRB New Orleans Child Development Center Building 528

| SAMPLING LOCATION DESCRIPTION | | | INITIAL SAMPLING RESULTS | | | RE-SAMPLING RESULTS | | | CORRECTIVE ACTIONS | POST REMEDIATION SAMPLING RESULTS | |
|---------------------------------|-----------|--------------------|----------------------------|------------------|------------------------------------|------------------------------------------------------------------------------------------------|------------------|------------------------------------------------------------------------|--------------------|-----------------------------------|------------------------------------------------------------------------|
| CATEGORY Water Intended For: | SAMPLE ID | Outlet Description | Recommended Level = 15 ppb | | | | | | | Recommended Level = 15 ppb | |
| | | | First Draw (ppb) | Retest required? | Date Fixture Secured? (See Note 1) | Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb) | First Draw (ppb) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) | Description | First Draw (ppb) (See note 2) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) |
| SAMPLING DATE | | | 6/8/2019 | | | mm/dd/yyyy | 7/2/2019 | 7/2/2019 | | 8/22/2019 | |
| RESULTS DATE | | | 6/24/2019 | | | mm/dd/yyyy | 7/10/2019 | 7/10/2019 | | 8/30/2019 | |

Table 2. Summary Statistics

| CATEGORY | INITIAL SAMPLING RESULTS | RE-SAMPLING RESULTS | | | POST REMEDIATION RESULTS |
|---------------------------|----------------------------|----------------------------------------------------------------------------------------|------------------|------------------------------------------------------------------------|--------------------------|
| | Recommended Level = 15 ppb | | | | |
| | First Draw (ppb) | Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb) | First Draw (ppb) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) | First Draw (ppb) |
| Total Drinking | 9 | 0 | 0 | 0 | 0 |
| Total Drinking > 15 ppb | 0 | 0 | 0 | 0 | 0 |
| Total Cook/Brush | 5 | 0 | 0 | 0 | 0 |
| Total Cook/Brush > 15 ppb | 0 | 0 | 0 | 0 | 0 |
| Total Washing | 53 | 0 | 1 | 1 | 1 |
| Total Washing > 15 ppb | 1 | 0 | 1 | 0 | 0 |
| Total Samples | 67 | 0 | 1 | 1 | 1 |
| Total Samples > 15 ppb | 1 | 0 | 1 | 0 | 0 |