

Priority Areas Lead Testing and Corrective Actions May 2019  
NAS Key West Child Development Center Building V-4187

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)		Recommended Level = 15 ppb	
									Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			5/18/2019			mm/dd/yyyy	6/13/2019	6/13/2019		8/1/2019	
RESULTS DATE			6/5/2019			mm/dd/yyyy	6/19/2019	6/19/2019		8/7/2019	
DRINKING	KW-V4187-LOBBY-WFC-A-FD (BLDG 4187-2)	Outside lobby restroom - Dual water fountains in lobby near restroom	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	KW-V4187-LOBBY-WFC-B-FD (BLDG 4187-3)	Outside lobby restroom - Dual water fountains in lobby near restroom	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING/TEETHBRUSHING	KW-V4187-RM133-RM-TB-A-FD (BLDG 4187-15)	Pre-toddler Room 1 - Low, single faucet open sink in classroom used for teeth brushing.	1.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING/TEETHBRUSHING	KW-V4187-RM130-RM-TB-FD (BLDG 4187-16)	Pre-toddler Room 2 - Low, single faucet open sink in classroom used for teeth brushing.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING/TEETHBRUSHING	KW-V4187-RM128-RM-TB-A-FD (BLDG 4187-24)	Pre-toddler Room 3 - Low, single faucet open sink in classroom used for teeth brushing.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING/TEETHBRUSHING	KW-V4187-RM125-RM-TB-FD (BLDG 4187-25)	Pre-toddler Room 4 - Low, single faucet open sink in classroom used for teeth brushing.	26	Yes	6/10/2019	N/A	8.7	0.92	Faucet was replaced on 22 June and passivation was performed for a period of three weeks.	1.2	N/A
COOKING/TEETHBRUSHING	KW-V4187-RM119-RM-TB-FD (BLDG 4187-33)	Toddler Room 1 - Low, single faucet open sink in classroom used for teeth brushing.	1.0	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING/TEETHBRUSHING	KW-V4187-RM116-RM-TB-FD (BLDG 4187-34)	Toddler Room 2 - Low, single faucet open sink in classroom used for teeth brushing.	2.8	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING/TEETHBRUSHING	KW-V4187-RM114-RM-TB-FD (BLDG 4187-43)	Pre-school Room 1 - Low, single faucet open sink in classroom used for teeth brushing.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions May 2019  
 NAS Key West Child Development Center Building V-4187

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 15 ppb				Description	First Draw (ppb) (See note 2)
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)			
SAMPLING DATE			5/18/2019			mm/dd/yyyy	6/13/2019	6/13/2019		8/1/2019	
RESULTS DATE			6/5/2019			mm/dd/yyyy	6/19/2019	6/19/2019		8/7/2019	
COOKING/TEETHBRUSHING	KW-V4187-RM105-RM-TB-FD (BLDG 4187-55)	Pre-school Room 2 - Low, single faucet open sink in classroom used for teeth brushing.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions May 2019  
NAS Key West Child Development Center Building V-4187

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 15 ppb							Recommended Level = 15 ppb	
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
<b>SAMPLING DATE</b>			<b>5/18/2019</b>			<b>mm/dd/yyyy</b>	<b>6/13/2019</b>	<b>6/13/2019</b>		<b>8/1/2019</b>	
<b>RESULTS DATE</b>			<b>6/5/2019</b>			<b>mm/dd/yyyy</b>	<b>6/19/2019</b>	<b>6/19/2019</b>		<b>8/7/2019</b>	
COOKING/TEETHBRUSHING	KW-V4187-RM102-RM-TB-FD (BLDG 4187-56)	Pre-school Room 3 - Low, single faucet open sink in classroom used for teeth brushing.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	KW-V4187-RM142-LOUNGE-K-FD (BLDG 4187-4)	Teachers Lounge - Kitchen sink on right side of room in lounge	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	KW-V4187-RM108-K-K-A-FD (BLDG 4187-46)	Kitchen - First faucet on double sink used for dishes and filling water coolers.	0.77	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	KW-V4187-RM108-K-K-B-FD (BLDG 4187-47)	Kitchen - Second faucet on double sink used for dishes and filling water coolers.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	KW-V4187-RM108-K-K-C-FD (BLDG 4187-48)	Kitchen - Small center island food prep sink.	9.8	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	KW-V4187-RM108-K-K-D-FD (BLDG V4187-49)	Kitchen, Larger food prep sink in back of room on the right side.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	KW-V4187-RM108-K-HHW-FD (BLDG 4187-50)	Kitchen - Hand washing sink on middle of right side of kitchen	1.7	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	KW-V4187-RM108-K-KA-FD (BLDG V4187-51)	Kitchen, Kitchen Sprayer	Non Detect	NO	N/A	N/A	N/A	N/A	Noted a second sprayer on site. This sprayer was noted as Sprayer A.	N/A	N/A
COOKING	KW-V4187-RM108-K-KB-FD (BLDG V4187-63)	Kitchen, Kitchen Sprayer	Non Detect	No	N/A	N/A	N/A	N/A	Second sprayer noted in kitchen. Designated as Sprayer B.	N/A	N/A
WASHING	KW-V4187-LOBBY-BATH-HHW-FD (BLDG 4187-1)	Lobby restroom - Combined restroom in CDC Lobby	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM142-BATH-HHW-FD (Bldg. V4187-5)	Teachers Lounge, Teachers Bathroom	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM141-RM-HHW-A-FD (BLDG 4187-6)	Infant Room 1 - Double stainless steel sink in shared changing area.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions May 2019  
NAS Key West Child Development Center Building V-4187

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 15 ppb					
First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)				Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
<b>SAMPLING DATE</b>			<b>5/18/2019</b>			<b>mm/dd/yyyy</b>	<b>6/13/2019</b>	<b>6/13/2019</b>		<b>8/1/2019</b>	
<b>RESULTS DATE</b>			<b>6/5/2019</b>			<b>mm/dd/yyyy</b>	<b>6/19/2019</b>	<b>6/19/2019</b>		<b>8/7/2019</b>	
WASHING	KW-V4187-RM141-RM-HHW-B-FD (BLDG 4187-7)	Infant Room 1 - Single stainless steel sink on Rm 139 side of shared changing area	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM141-RM-HHW-C-FD (BLDG 4187-8)	Infant Room 1 - Single stainless steel sink on Rm 141 side of shared changing area	1.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM138-RM-HHW-A-FD (BLDG 4187-9)	Infant Room 2 - Double stainless steel sink in shared changing area.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM138-RM-HHW-B-FD (BLDG 4187-10)	Infant Room 2 - Single stainless steel sink on Rm 136 side of shared changing area	1.8	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM138-RM-HHW-C-FD (BLDG 4187-11)	Infant Room 2 - Single stainless steel sink on Rm 138 side of shared changing area	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM133-RM-HHW-A-FD (BLDG 4187-12)	Pre-toddler Room 1 - Single stainless steel sink on Rm 133 side of shared changing area	2.2	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM133-RM-HHW-B-FD (BLDG 4187-13)	Pre-toddler Room 1 - Stainless steel sink outside changing area and child's bathroom.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM133-RM-LHW-FD (BLDG 4187-14)	Pre-toddler Room 1 - Child's bathroom sink	1.4	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM130-RM-LHW-FD (BLDG 4187-17)	Pre-toddler Room 2 - Child's bathroom sink	6.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM130-RM-HHW-A-FD (BLDG 4187-18)	Pre-toddler Room 2 - Stainless steel sink outside changing area and child's bathroom.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions May 2019  
 NAS Key West Child Development Center Building V-4187

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			Recommended Level = 15 ppb			Recommended Level = 15 ppb		Recommended Level = 15 ppb			
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
<b>SAMPLING DATE</b>			<b>5/18/2019</b>			<b>mm/dd/yyyy</b>	<b>6/13/2019</b>	<b>6/13/2019</b>		<b>8/1/2019</b>	
<b>RESULTS DATE</b>			<b>6/5/2019</b>			<b>mm/dd/yyyy</b>	<b>6/19/2019</b>	<b>6/19/2019</b>		<b>8/7/2019</b>	
WASHING	KW-V4187-RM130-RM-HHW-B-FD (BLDG 4187-19)	Pre-toddler Room 2 - Single stainless steel sink on Rm 130 side of shared changing area	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM128-RM-HHW-A-FD (BLDG 4187-20)	Pre-toddler Room 3 - Single stainless steel sink on Rm 128 side of shared changing area	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions May 2019  
NAS Key West Child Development Center Building V-4187

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 15 ppb					
First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)				Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
<b>SAMPLING DATE</b>			<b>5/18/2019</b>			<b>mm/dd/yyyy</b>	<b>6/13/2019</b>	<b>6/13/2019</b>		<b>8/1/2019</b>	
<b>RESULTS DATE</b>			<b>6/5/2019</b>			<b>mm/dd/yyyy</b>	<b>6/19/2019</b>	<b>6/19/2019</b>		<b>8/7/2019</b>	
WASHING	KW-V4187-RM128-RM-HHW-B-FD (BLDG 4187-21)	Pre-toddler Room 3 - Stainless steel sink outside changing area and child's bathroom.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM128-HOSE-FD (BLDG 4187-22)	Pre-toddler Room 3. Hose on outside from Room 128	14	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM128-RM-LHW-FD (BLDG 4187-23)	Pre-toddler Room 3 - Child's bathroom sink	3.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM125-RM-LHW-FD (BLDG 4187-26)	Pre-toddler Room 4 - Child's bathroom sink	9.8	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM125-RM-HHW-A-FD (BLDG 4187-27)	Pre-toddler Room 4 - Stainless steel sink outside changing area and child's bathroom.	1.7	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM125-RM-HHW-B-FD (BLDG 4187-28)	Pre-toddler Room 4 - Single stainless steel sink on Rm 125 side of shared changing area	6.2	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM119-RM-HHW-A-FD (BLDG 4187-29)	Toddler Room 1 - Single stainless steel sink on Rm 119 side of shared area	2.8	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM119-RM-HHW-B-FD (BLDG 4187-30)	Toddler Room 1 - Stainless steel sink outside shared area and child's bathroom.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM119-RM-LHW-A-FD (BLDG 4187-31)	Toddler Room 1 - Child's bathroom sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM119-RM-LHW-B-FD (BLDG 4187-32)	Toddler Room 1 - Child's bathroom sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM116-RM-LHW-A-FD (BLDG 4187-35)	Toddler Room 2 - Child's bathroom sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM116-RM-LHW-B-FD (BLDG 4187-36)	Toddler Room 2 - Child's bathroom sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM116-RM-HHW-A-FD (BLDG 4187-37)	Toddler Room 2 - Stainless steel sink outside shared area and child's bathroom.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions May 2019  
NAS Key West Child Development Center Building V-4187

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			Recommended Level = 15 ppb							Recommended Level = 15 ppb	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
<b>SAMPLING DATE</b>			<b>5/18/2019</b>			<b>mm/dd/yyyy</b>	<b>6/13/2019</b>	<b>6/13/2019</b>		<b>8/1/2019</b>	
<b>RESULTS DATE</b>			<b>6/5/2019</b>			<b>mm/dd/yyyy</b>	<b>6/19/2019</b>	<b>6/19/2019</b>		<b>8/7/2019</b>	
WASHING	KW-V4187-RM116-RM-HHW-B-FD (BLDG 4187-38)	Toddler Room 2 - Single stainless steel sink on Rm 116 side of shared area	2.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM116-HOSE-FD (BLDG 4187-39)	Toddler Room 2. Hose on Outside from Room 116	5.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM114-RM-LHW-A-FD (BLDG 4187-40)	Pre-school Room 1 - Child's bathroom sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM114-RM-LHW-B-FD (BLDG 4187-41)	Pre-school Room 1 - Child's bathroom sink	0.86	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM114-RM-HHW-FD (BLDG 4187-42)	Pre-school Room 1 - Stainless steel sink outside child's bathroom.	2.1	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM111-RM-HHW-FD (BLDG 4187-44)	Training Room - Stainless steel sink	29	Yes	6/10/2019	N/A	120	3.2	Faucet was replaced on 22 June and passivation was performed for a period of three weeks.	0.56	N/A
WASHING	KW-V4187-RM111-RM-LHW-FD (BLDG V4187-45)	Training Room - Stainless steel sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM105-RM-HHW-FD (BLDG 4187-52)	Pre-school Room 2 - Near door to the room.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM105-RM-LHW-A-FD (BLDG 4187-53)	Pre-school Room 2 - Boys bathroom sink.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM105-RM-LHW-B-FD (BLDG 4187-54)	Pre-school Room 2 - Girls bathroom sink.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM102-RM-LHW-A-FD (BLDG 4187-57)	Pre-school Room 3 - Boys bathroom sink.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM102-RM-LHW-B-FD (BLDG 4187-58)	Pre-school Room 3 - Girls bathroom sink.	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-RM102-RM-HHW-FD (BLDG 4187-59)	Pre-school Room 3 - Near door to the room.	1.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-PLAYGD-HOSE-FD (BLDG V4187-60)	Playground, On outside of bldg. at playground	4.3	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KW-V4187-BLDGFT-HOSE-FD (BLDG V4187-61)	Building Entrance. Hose on outside of building at entrance	2.4	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions May 2019  
 NAS Key West Child Development Center Building V-4187

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 15 ppb				Description	First Draw (ppb) (See note 2)
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)			
SAMPLING DATE			5/18/2019			mm/dd/yyyy	6/13/2019	6/13/2019			8/1/2019
RESULTS DATE			6/5/2019			mm/dd/yyyy	6/19/2019	6/19/2019			8/7/2019
WASHING	KW-BLDGBK-HOSE-FD (BLDG V4187-62)	Building Rear. Hose outlet on rear of building	1.8	NO	N/A	N/A	N/A	N/A		N/A	N/A

Notes:  
 1 Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 15 ppb.



Priority Areas Lead Testing and Corrective Actions May 2019  
 NAS Key West Child Development Center Building V-4187

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 15 ppb				Description	Recommended Level = 15 ppb
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb) (See note 2)		Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			5/18/2019			mm/dd/yyyy	6/13/2019	6/13/2019		8/1/2019	
RESULTS DATE			6/5/2019			mm/dd/yyyy	6/19/2019	6/19/2019		8/7/2019	

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	First Draw (ppb)	Water Fountain	First Draw (ppb)	Follow up Flush	First Draw (ppb)
Total Drinking	2	0	0	0	0
Total Drinking >15 ppb	0	0	0	0	0
Total Cook/Brush	17	0	1	1	1
Total Cook/Brush >15 ppb	1	0	0	0	0
Total Washing	44	0	1	1	1
Total Washing >15 ppb	1	0	1	0	0
Total Samples	63	0	2	2	2
Total Samples >15 ppb	2	0	1	0	0