

Priority Areas Lead Testing and Corrective Actions May 2019
NAS KINGSVILLE OUTSIDE PLAY AREAS

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
			CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)		Recommended Level = 15 ppb	
Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)							Description		
SAMPLING DATE			5/18/2019			mm/dd/yyyy	6/14/2019	6/14/2019		9/12/2019	
RESULTS DATE			6/5/2019			mm/dd/yyyy	6/24/2019	6/24/2019		9/17/2019	
DRINKING	KVL-PLAY-4713-HOSE-FD (OPAs-1)	Hose spigot attached to softball field concession stand (Bldg 4713). Corner of Nimitz and Hutchins, across from Fitness Center	31	Yes	6-Jun-19		6.3	0.24	Fixture replaced on 9/9/2019.	0.59	N/A
DRINKING	KVL-PLAY-5738-WFBA-FD (OPAs-2)	Football field behind new gym by 40-yard line. Higher of two side by side fountains.	Non Detect	NO	N/A						
DRINKING	KVL-PLAY-5701-HOSE-FD (OPAs-3)	Hose bib attached to restroom building adjacent to tennis courts. Area of old fitness center.	53	Yes	6-Jun-19	N/A	N/A	N/A	Fixture permanently removed.	N/A	N/A
DRINKING	KVL-PLAY-4799-HOSE-FD (OPAs-4)	Hose bib attached to concession building by softball field. Area of old fitness center.	97	Yes	6-Jun-19	N/A	N/A	N/A	Fixture permanently removed.	N/A	N/A
DRINKING	KVL-PLAY-TENNIS-HOSE-FD (OPAs-5)	Hose bib by entrance to tennis courts. Area of old fitness center with tennis, basketball, and softball paly areas.	7.7	No							

Notes:

¹ Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 15 ppb.

² Post-remediation sampling was conducted on 9/12/19 and final results below recommended level of 15 ppb for sample collected as shown on the table.

Priority Areas Lead Testing and Corrective Actions May 2019
NAS KINGSVILLE OUTSIDE PLAY AREAS

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 15 ppb				Description	First Draw (ppb) (See note 2)
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)			
SAMPLING DATE			5/18/2019			mm/dd/yyyy	6/14/2019	6/14/2019		9/12/2019	
RESULTS DATE			6/5/2019			mm/dd/yyyy	6/24/2019	6/24/2019		9/17/2019	

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)
Total Drinking	5	0	1	1	1
Total Drinking > 15 ppb	3	0	0	0	0
Total Cook/Brush	0	0	0	0	0
Total Cook/Brush > 15 ppb	0	0	0	0	0
Total Washing	0	0	0	0	0
Total Washing > 15 ppb	0	0	0	0	0
Total Samples	5	0	1	1	1
Total Samples > 15 ppb	3	0	0	0	0