

Priority Areas Lead Testing and Corrective Actions May 2019  
NAS KINGSVILLE Youth Center Building 2742

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 15 ppb				Description	First Draw (ppb) (See note 2)
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)			
<b>SAMPLING DATE</b>			<b>5/18/2019</b>			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy			mm/dd/yyyy
<b>RESULTS DATE</b>			<b>6/5/2019</b>			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy			mm/dd/yyyy
DRINKING	KVL-2742-RM-WFC-FD (BLDG 2742-1)	Fountain between restrooms - Water Fountain	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
COOKING	KVL-2742-K-K-FD (BLDG 2742-6)	Kitchen sink	Non Detect	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KVL-2742-HALL-HHW-FD (BLDG 2742-2)	Handwash sink between restrooms by water fountain	4.7	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KVL-2742-BATH-W-HHW-FD (BLDG 2742-3)	Women's bathroom - Sink in women's restroom, left	2.9	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KVL-2742-BATH-M-HHW-FD (BLDG 2742-4)	Men's bathroom - Sink in men's restroom	1.9	NO	N/A	N/A	N/A	N/A		N/A	N/A
WASHING	KVL-2742-BATH-UNISEX-HHW-FD (BLDG 2742-5)	Restroom in kitchen area - Sink in unisex restroom	2.7	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions May 2019  
NAS KINGSVILLE Youth Center Building 2742

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 15 ppb				Description	First Draw (ppb) (See note 2)
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)			
SAMPLING DATE			5/18/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		
RESULTS DATE			6/5/2019			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS		RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	Recommended Level = 15 ppb					First Draw (ppb)
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)	
Total Drinking	1	0	0	0	0	0
Total Drinking > 15 ppb	0	0	0	0	0	0
Total Cook/Brush	1	0	0	0	0	0
Total Cook/Brush > 15 ppb	0	0	0	0	0	0
Total Washing	4	0	0	0	0	0
Total Washing > 15 ppb	0	0	0	0	0	0
Total Samples	6	0	0	0	0	0
Total Samples > 15 ppb	0	0	0	0	0	0