



NAVY AND MARINE CORPS PUBLIC HEALTH CENTER
PREVENTION AND PROTECTION START HERE

Navy and Marine Corps Public Health Center

Appendix Q **ACI Sampling Photographic Log**

April 2016

620 John Paul Jones Circle, Suite 1100
Portsmouth, VA 23708-2103



NAVY AND MARINE CORPS PUBLIC HEALTH CENTER

PREVENTION AND PROTECTION START HERE

This page has been left blank to allow for double-sided printing



Photographic Log

Table of Contents

Photo No. 1: ACI Sampling Event – April 2016	2
Photo No. 2: ACI Sampling Event – April 2016	2
Photo No. 3: ACI Sampling Event – April 2016	3
Photo No. 4: ACI Sampling Event – April 2016	3
Photo No. 5: ACI Sampling Event – April 2016	4
Photo No. 6: ACI Sampling Event – April 2016	4
Photo No. 7: ACI Sampling Event – April 2016	5
Photo No. 8: ACI Sampling Event – April 2016	5
Photo No. 9: ACI Sampling Event – April 2016	6
Photo No. 10: ACI Sampling Event – April 2016	6
Photo No. 11: ACI Sampling Event – April 2016	7
Photo No. 12: ACI Sampling Event – April 2016	7



Photographic Log

Photo No. 1: ACI
Sampling Event – April
2016

Date: April 2016

Emissions from the ACIs
seen in the background.
Picture was taken from
the 5th floor of the
Bachelor Officer's
Quarters – Facing
East/East-Northeast.



Photo No. 2: ACI
Sampling Event – April
2016

Date: April 2016

MSW burning in the ACI
that was sampled. The
temporary air sampling
"stack" is located on the
right side of the
photograph.





Photographic Log

Photo No. 3: ACI
Sampling Event – April
2016

Date: April 2016

MSW burning in the ACI
that was sampled. The
temporary air sampling
“stack” is located on the
left side of the
photograph.



Photo No. 4: ACI
Sampling Event – April
2016

Date: April 2016

MSW burning in the ACI
that was sampled. The
temporary air sampling
“stack” is located on the
left side of the
photograph.





Photographic Log

Photo No. 5: ACI Sampling Event – April 2016

Date: April 2016

MSW burning in the ACI that was sampled. The temporary air sampling "stack" is located on the left side of the photograph.



Photo No. 6: ACI Sampling Event – April 2016

Date: April 2016

MSW burning in an ACI. This ACI was not sampled during the April 2016 sampling event.





Photographic Log

Photo No. 7: ACI
Sampling Event – April
2016

Date: April 2016

MSW burning in the ACI
that was sampled. An
ash-pit is located on the
left side of the figure. Ash
is deposited in on-site pits
after combustion in the
ACIs.



Photo No. 8: ACI
Sampling Event – April
2016

Date: April 2016

MSW burning in the ACI
that was sampled. The
temporary air sampling
“stack” is located on the
left side of the
photograph.





Photographic Log

Photo No. 9: ACI
Sampling Event – April
2016

Date: April 2016

MSW burning in ACIs.
These ACIs were not
sampled during the April
2016 sampling event.



Photo No. 10: ACI
Sampling Event – April
2016

Date: April 2016

MSW burning in the ACI
that was sampled. An
ash-pit is located on the
left side of the figure. Ash
is deposited in on-site pits
after combustion in the
ACIs.





Photographic Log

Photo No. 11: ACI Sampling Event – April 2016

Date: April 2016

MSW burning in the ACI that was sampled. The temporary air sampling "stack" is located on the left side of the photograph.



Photo No. 12: ACI Sampling Event – April 2016

Date: April 2016

MSW burning in ACIs that were not sampled during the April 2016 sampling event.

