

Priority Areas Lead Testing and Corrective Actions September 2018
Naval Support Activity MID-SOUTH Outside Play Areas

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	Recommended Level = 20ppb							Description	Recommended Level = 20ppb
			First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb) (See note 2)		Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE			8/18/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
RESULTS DATE			9/7/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		mm/dd/yyyy	
DRINKING	MDS-1903-PLAY-WFBA-FD (OPA-1)	Splash Park Stand alone fountain by soda machine/restrooms	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-1903-PLAY-WFBC-FD (OPA-3)	Splash Park Attached fountains on west side of splash pad, middle	1.7	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-1903-PLAY-WFBD-FD (OPA-4)	Splash Park Attached fountains on west side of splash pad, right	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-1784-PLAY-WFBD-FD (OPA-5)	Baseball Field Across Splash Park - Fountain attached to restroom building	Not Detected	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-499-PLAY-WFBA-FD (OPA-6)	Basketball Courts Across from Fitness Center -High/Low Combination Fountain, left low fountain	6.7	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-499-PLAY-WFBB-FD (OPA- 7)	Basketball Courts Across from Fitness Center -High/Low Combination Fountain, right high fountain	Not Detected (Sample taken 9/19/18)	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-499-PLAY-WFBC-FD (OPA- 8)	Basketball Courts Across from Fitness Center - Stand Alone Fountain	6.6	NO	N/A	N/A	N/A	N/A		N/A	N/A
DRINKING	MDS-499-PLAY-HOSE-FD (OPA- 9)	Basketball Courts Across from Fitness Center - Hose Attachment connected to Stand Alone Fountain	9	NO	N/A	N/A	N/A	N/A		N/A	N/A

Priority Areas Lead Testing and Corrective Actions September 2018
Naval Support Activity MID-SOUTH Outside Play Areas

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS			RE-SAMPLING RESULTS			CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Recommended Level = 20ppb				Description	First Draw (ppb) (See note 2)
						Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)			
SAMPLING DATE			8/18/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		
RESULTS DATE			9/7/2018			mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy	mm/dd/yyyy		

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS			POST REMEDIATION RESULTS
	First Draw (ppb)	Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)
Total Drinking	8	0	0	0	0
Total Drinking > 20 ppb	0	0	0	0	0
Total Cook/Brush	0	0	0	0	0
Total Cook/Brush > 20 ppb	0	0	0	0	0
Total Washing	0	0	0	0	0
Total Washing > 20 ppb	0	0	0	0	0
Total Samples	8	0	0	0	0
Total Samples > 20 ppb	0	0	0	0	0